

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	INCOME INSURAN	ICE LTD	Ref:	CS/INC23003347/Sqy3	
	75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557		Date:	30/03/2023	
			Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKT 7673B	Veh. Inspected	SLR 3345Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1215590-002	Excess (\$)	0.00	
	Assign From	JURAIDAH ABBAS	Assign Date	30/03/2023	
2. Vehicle Particulars & Condition					
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer -		Steering		
	Brakes		Modification		
	General				
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
5.	5. General Information				
	Accident Date	23/03/2023	Inspection Date	30/03/2023	
	Survey held at	AP AUTOMOTIVE SERVICES PTE LTD			
		9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840			
5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				