



1

of 2 ?



100%



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01 SINGAPORE 068897

Ref: CS3/AIS23003363/y3

Date: 31/03/2023

Code: AIS

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SFL 111D	Veh. Inspected	GBH 969P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	SHANTI	Assign Date	30/03/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/03/2023	Inspection Date	31/03/2023
Survey held at	HUI WANG ENTERPRISE BLK 5 DEFU LANE 10 #01-576 SINGAPORE 539187		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--