



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 S737896

HP: 98888885

Estimation

Date:

30/3/2023

Vehicle:

SLE6073G

Make / Model:

TOYOTA ALTIS

INS:

FIRST CAPITAL

Not Authorized
11/3/23 11:50h
Penny After Paint
4 days

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	SIDE MIRROR	1	\$ 685.00	\$ 685.00
2	FRONT FENDER RH	1	\$ 698.00	\$ 698.00
3	FRONT FENDER COWLING RH	1	\$ 159.00	\$ 159.00
4	FRONT FENDER EMBLEM 'HYBRID'	1	\$ 62.00	\$ 62.00
5	FRONT DOOR RH	1	\$ 1,398.00	\$ 1,398.00
6	FRONT DOOR OUTER MOULDING RH	1	\$ 159.00	\$ 159.00
7	FRONT BUMPER	1	\$ 687.00	\$ 687.00
TOTAL PART				\$ 3,848.00
LIST DOWN				\$ 962.00
AFTER LIST DOWN				\$ 2,886.00
SPECIAL NETT				
1	FRT FENDER INNERSHIELD CLIP SET LH	1	\$ 50.00	\$ 50.00
2	FRT FENDER QUARTER GLASS SEALANT LH	1	\$ 80.00	\$ 80.00
3	FRONT DOOR INNER TRIM CLIPS	1	\$ 50.00	\$ 50.00
TOTAL AMOUNT				\$ 180.00
LABOUR				
1	CHECK WIRING	1	\$ 100.00	\$ 100.00
2	R+R FRONT DOOR MECHANISM	1	\$ 200.00	\$ 200.00
3	WHEEL ALIGNMENT	1	\$ 120.00	\$ 120.00
4	R+R FRT FENDER QUARTER GLASS LH	1	\$ 120.00	\$ 120.00
5	RESET TROUBLE CODE	1	\$ 200.00	\$ 200.00
6	KNOCK	1	\$ 500.00	\$ 500.00
7	SPRAY	1	\$ 800.00	\$ 800.00
TOTAL AMOUNT				\$ 2,040.00
Parts Replacement Amount				\$ 3,653.25
Total Amount for Labour				\$ 2,040.00
Total Amount				\$ 5,693.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: