

SERVICE ESTIMATE

80489 - C00001
Mr Tan Kian Meng
6 Pasir Ris View

SL: SERVICE SALES - PC

Singapore 518589

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Tan Kian Meng

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 30/03/2023
WIP No. . : 13473
Veh.In/Out:
*Tel.No. . : Mobile: 96714348
Reg.No. . : SFA606B
Reg.date . : 30/08/2019
Mileage .. : 0
Chassis No: SALWA2AU8KA871111

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
R16	TOWING CHARGE 27/03/2023	0	250.00	0		250.00	S
802	TO REPLACE BONNET, FRT BUMPER,	0	15000.00	0		15,000.00	S
	RADIATOR GRILLE, MESH GRILLE LOWER @1300 X 5					6500	
	MESH GRILLE RH, RHF FENDER, RHF						
	FENDER APRON, RHF WHEEL HOUSE,						
	FRT SUPPORT PANEL, RHF FRAME BRACKET,						
	HEADLAMP RH/LH, ETC						
800	TO BLEND & SPRAY PAINT @1000 X 4	0	7500.00	0		7,500.00	S
	BONNET, FRT BUMPER, INSERT RH,					4000	
	TOWING COVER, RHF FENDER,					1000	
	RHF FENDER APRON, RHF WHEEL HOUSE,						
	RHF DOOR						
802	TO REMOVE & REFIT WIPER COWLIN	0	1500.00	0		1,500.00	S
ETC							
802	TO REPLACE FRT WINDSCREEN,	0	1300.00	0		1,300.00	S
ETC							
0080	TO INSTALL FRT WINDSCREEN FILM	0	280.00	0		280.00	S

SERVICE ESTIMATE

80489 - C00001
Mr Tan Kian Meng
6 Pasir Ris View

SL: SERVICE SALES - PC

Singapore 518589

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Tan Kian Meng

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 30/03/2023
WIP No. . : 13473
Veh.In/Out:
*Tel.No. . : Mobile: 96714348
Reg.No. . : SFA606B
Reg.date . : 30/08/2019
Mileage .. : 0
Chassis No: SALWA2AU8KA871111

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	621.00	0		621.00	S
280	TO FOCUS HEADLAMP	0	207.00	0		207.00	S
802	TO VACUUM & TOP UP AIRCON GAS	0	600.00	0		600.00	S
287	TO REPLACE RHF UNDERCARRIAGE	0	6624.00	0		6,624.00	S
ETC						3312	
287	TO REPLACE STEERING RACK, CROSSMEMBER, ETC	0	6624.00	0		6,624.00	S
419	WHEEL ALIGNMENT	0	280.00	0		280.00	S
0031	TO REPLACE RHF TYRE	0	900.00	0		900.00	S
0031	TO REPLACE RHF RIM	0	50.00	0		50.00	S
287	TO REMOVE & REFIT DASHBOARD	0	8280.00	0		8,280.00	S
PILLAR TRIMS, FITTING, CARPET, SEAT CONSULE, ETC TO GIVE WAY REPAIR.						6624	
R06	NUMBER PLATE & HOLDER	0	60.00	0		60.00	S
802	TO REPLACE CONDENSER, RADIATOR	0	2500.00	0		2,500.00	S

SERVICE ESTIMATE

80489 - C00001
Mr Tan Kian Meng
6 Pasir Ris View

SL: SERVICE SALES - PC

Singapore 518589

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Tan Kian Meng

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 3
Inv.date. : 30/03/2023
WIP No. . : 13473
Veh.In/Out:
*Tel.No. . : Mobile: 96714348
Reg.No. . : SFA606B
Reg.date . : 30/08/2019
Mileage ... : 0
Chassis No: SALWA2AU8KA871111

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
ETC							
	V000008921/IU STICKE <i>in</i>	1.0 EA	6.90			6.90	S
	D PRIMER GLASS & PP <i>in</i>	1.0 EA	46.90			46.90	S
	ADHESIVE AND SEALER <i>in</i>	2.0 EA	192.90			385.80	S
	GLASS - WINDSCREEN <i>in photo</i>	1.0 EA	3035.80			3,035.80	S
	MODULE - WINDSHIELD <i>in</i>	1.0 EA	701.30			701.30	S
	LH FINISHER - 'A' PI <i>in</i>	1.0 EA	272.20			272.20	S
	A PILLAR FINISHER RH <i>in</i>	1.0 EA	272.20			272.20	S
	HOOD <i>repair</i>	1.0 EA	6090.80			6,090.80	S
	GRILLE - HOOD VENT L X	1.0 EA	3732.40			3,732.40	S
	GRILLE - HOOD VENT R X	1.0 EA	3732.40			3,732.40	S
	GUIDE - DIRTY AIR DU ?	2.0 EA	69.90			139.80	S
	BONNET CABLE CLIP <i>in</i>	10.0 EA	5.10			51.00	S
	BONNET SEAL RRS3 X	1.0 EA	260.60			260.60	S
	BONNET SEAL INNER RR X	1.0 EA	355.40			355.40	S
	BONNET STRUT RRS3 X	1.0 EA	131.30			131.30	S
	HINGE - HOOD RH X	1.0 EA	307.30			307.30	S

SERVICE ESTIMATE

80489 - C00001
Mr Tan Kian Meng
6 Pasir Ris View

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 4

Inv.date. : 30/03/2023

WIP No. . : 13473

Veh.In/Out:

*Tel.No. . : Mobile: 96714348

Reg.No. . : SFA606B

Reg.date . : 30/08/2019

Mileage . : 0

Chassis No: SALWA2AU8KA871111

Singapore 518589

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Mr Tan Kian Meng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	RH BRACKET - HOOD ST <i>X</i>	1.0 EA	37.30			37.30	S
	REINFORCEMENT - FRON <i>bt</i>	1.0 EA	1045.50			1,045.50	S
	BRACKET - BUMPER MOU <i>cm</i>	1.0 EA	270.80			270.80	S
	BRACKET - LICENSE PL <i>X</i>	1.0 EA	92.40			92.40	S
	BRACKET - BUMPER MOU <i>cm</i>	1.0 EA	264.20			264.20	S
	BRACKET - BUMPER MOU <i>cm</i>	1.0 EA	103.90			103.90	S
	BUMPER - FRONT <i>tom</i>	1.0 EA	3320.20			3,320.20	S
	GRILLE - BUMPER <i>cm</i>	1.0 EA	557.10			557.10	S
	COVER - TOW HOOK <i>ms</i>	1.0 EA	669.70			669.70	S
	DEFLECTOR - AIR <i>cm</i>	1.0 EA	230.70			230.70	S
	RH BRACKET - BUMPER <i>cm</i>	1.0 EA	205.40			205.40	S
	RH BRACKET - BUMPER <i>cm</i>	1.0 EA	43.60			43.60	S
	CAP - POWERWASH JET <i>ms</i>	1.0 EA	55.00			55.00	S
	PLATE - BLANKING RH <i>ms</i>	1.0 EA	114.30			114.30	S
	KIT - BUMPER VENTS <i>ms</i>	1.0 EA	618.80			618.80	S
	GRILLE - BUMPER RH <i>ms</i>	1.0 EA	533.80			533.80	S
	RH DUCT - BRAKE CALI <i>ms</i>	1.0 EA	514.60			514.60	S

SERVICE ESTIMATE

80489 - C00001
Mr Tan Kian Meng
6 Pasir Ris View

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 5

Inv.date. : 30/03/2023

WIP No. . : 13473

Veh.In/Out:

*Tel.No. . : Mobile: 96714348

Reg.No. . : SFA606B

Reg.date . : 30/08/2019

Mileage . : 0

Chassis No: SALWA2AU8KA871111

Singapore 518589

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Mr Tan Kian Meng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	INSERT - BUMPER RH <i>mis</i>	1.0 EA	344.60			344.60	S
	RH DEFLECTOR - AIR <i>mis</i>	1.0 EA	119.30			119.30	S
	GRILLE - RADIATOR <i>cm</i>	1.0 EA	2982.70			2,982.70	S
	GRILLE STUD DIS4 <i>ne</i>	10.0 EA	11.00			110.00	S
	RIVET <i>ne</i>	10.0 EA	10.30			103.00	S
	FRONT GRILLE "LR" LO <i>ne</i>	1.0 EA	163.10			163.10	S
	"RANGE" NAME PLATE - <i>ne</i>	1.0 EA	325.50			325.50	S
	"ROVER" NAME PLATE - <i>ne</i>	1.0 EA	338.10			338.10	S
	RH HEADLAMP AND FLAS <i>bro</i>	1.0 EA	12177.90			12,177.90	S
	RH LAMP - FOG - FRON <i>mis</i>	1.0 EA	867.40			867.40	S
	FRAME PANEL RRS3 <i>ca</i>	1.0 EA	1206.60			1,206.60	S
	RH BRACKET - FRONT E <i>mis</i>	1.0 EA	94.90			94.90	S
	RH SHIELD - SPLASH - <i>de</i>	1.0 EA	221.50			221.50	S
	RH SHIELD - SPLASH - <i>mis</i>	1.0 EA	429.90			429.90	S
	FENDER - FRONT RH <i>huc</i>	1.0 EA	2226.10			2,226.10	S
	RH GRILLE - FENDER - <i>ne</i>	1.0 EA	1988.20			1,988.20	S
	RH BRACKET - FENDER <i>mis</i>	1.0 EA	86.10			86.10	S

SERVICE ESTIMATE

80489 - C00001
Mr Tan Kian Meng
6 Pasir Ris View

SL: SERVICE SALES - PC

Singapore 518589

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Tan Kian Meng

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 6
Inv.date. : 30/03/2023
WIP No. . : 13473
Veh.In/Out:
*Tel.No. . : Mobile: 96714348
Reg.No. . : SFA606B
Reg.date . : 30/08/2019
Mileage ... : 0
Chassis No: SALWA2AU8KA871111

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	INSULATOR - FOAM PAD <i>cm</i>	1.0 EA	86.80			86.80	S
	SCREW <i>m</i>	10.0 EA	3.10			31.00	S
	RH DEFLECTOR - AIR - <i>cm</i>	1.0 EA	313.10			313.10	S
	RH DEFLECTOR - AIR <i>cm</i>	1.0 EA	186.10			186.10	S
	DEFLECTOR - AIR - RA <i>cm</i>	1.0 EA	431.30			431.30	S
	SHUTTER - RADIATOR C <i>cm</i>	1.0 EA	529.60			529.60	S
	AIR DEFLECTOR RH RRS <i>cm</i>	1.0 EA	50.80			50.80	S
	AIR DEFLECTOR RRS3 R <i>cm</i>	1.0 EA	688.50			688.50	S
	DEFLECTOR - AIR - RA <i>cm</i>	1.0 EA	490.50			490.50	S
	COVER ?	1.0 EA	111.00			111.00	S
	RH BRACKET - ENGINE ?	1.0 EA	19.60			19.60	S
	RH COVER - ENGINE CO ?	1.0 EA	57.40			57.40	S
	RH MOULDING - SNOW I ?	1.0 EA	68.00			68.00	S
	RH MOULDING - FENDER ?	1.0 EA	243.80			243.80	S
	RH KIT - HOSE AND WAM <i>m</i>	1.0 EA	116.30			116.30	S
	LH KIT - HOSE AND WAM <i>m</i>	1.0 EA	96.10			96.10	S
	RESERVOIR - WINDSHIE <i>X</i>	1.0 EA	653.90			653.90	S

SERVICE ESTIMATE

80489 - C00001
Mr Tan Kian Meng
6 Pasir Ris View

SL: SERVICE SALES - PC

Singapore 518589

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Tan Kian Meng

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 7
Inv.date. : 30/03/2023
WIP No. . : 13473
Veh.In/Out:
*Tel.No. . : Mobile: 96714348
Reg.No. . : SFA606B
Reg.date . : 30/08/2019
Mileage .. : 0
Chassis No: SALWA2AU8KA871111

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	RH CLEANER - AIR <i>cm</i>	1.0 EA	946.30			946.30	S
	RH DUCT - DIRTY AIR <i>de</i>	1.0 EA	538.90			538.90	S
	RH DUCT - AIR <i>de</i> ?	1.0 EA	197.60			197.60	S
	SHROUD - RADIATOR FA ?	1.0 EA	706.70			706.70	S
	RADIATOR ?	1.0 EA	2026.90			2,026.90	S
	MOTOR AND FAN - ENGI ?	1.0 EA	3412.90			3,412.90	S
	FAN AND MOTOR ?	1.0 EA	2095.50			2,095.50	S
	RADIATOR AUXILIARY R ?	1.0 EA	900.80			900.80	S
	BRACKET - RADIATOR ?	1.0 EA	104.30			104.30	S
	SENSOR - PARKING AID <i>h</i>	3 1.0 EA	383.80			1,535.20	S
	SENSOR - PARKING AID <i>x</i>	1.0 EA	478.90			478.90	S
	WIRING - BUMPER FRT <i>cut</i>	1.0 EA	595.80			595.80	S
	CAMERA - PARKING ?	1.0 EA	1583.10			1,583.10	S
	COOLANT 1L ?	4.0 EA	72.20			288.80	S
	ENGINE BAY HARNESS <i>cut</i>	1.0 EA	8144.40			8,144.40	S
	SHIELD - ENGINE COMP ?	1.0 EA	473.60			473.60	S
	SHIELD - SPLASH RH ?	1.0 EA	171.90			171.90	S

SERVICE ESTIMATE

80489 - C00001
Mr Tan Kian Meng
6 Pasir Ris View

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 8

Inv.date. : 30/03/2023

WIP No. . : 13473

Veh.In/Out:

*Tel.No. . : Mobile: 96714348

Reg.No. . : SFA606B

Reg.date . : 30/08/2019

Mileage ... : 0

Chassis No: SALWA2AU8KA871111

Singapore 518589

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Mr Tan Kian Meng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BRACKET - HEATSHIELD ?	1.0 EA	21.00			21.00	S
	CONDENSER ?	1.0 EA	1933.60			1,933.60	S
	LH HEADLAMP AND FLAS X	1.0 EA	12177.90			12,177.90	S
	GEAR - STEERING sw / ?	1.0 EA	13013.10			13,013.10	S
	RH KNUCKLE - FRONT W ?	1.0 EA	3166.00			3,166.00	S
	RH DUCT - BRAKE CALI ?	1.0 EA	430.20			430.20	S
	RH DUCT - BRAKE DISC ?	1.0 EA	50.20			50.20	S
	RH ARM - FRONT SUSPE ?	1.0 EA	865.50			865.50	S
	RH ARM - FRONT SUSPE ?	1.0 EA	527.40			527.40	S
	RH ARM - FRONT SUSPE ?	1.0 EA	795.30			795.30	S
	STABILIZER LINK FRT ?	1.0 EA	195.80			195.80	S
	BAR - STABILIZER ?	1.0 EA	765.60			765.60	S
	MACPHERSON STRUT ?	1.0 EA	4065.20			4,065.20	S
	YOKE - SUSPENSION RH ?	1.0 EA	1029.40			1,029.40	S
	DRIVESHAFT NUT M24X2 ?	1.0 EA	33.50			33.50	S
	WHEEL - ALLOY ?	1.0 EA	3209.70			3,209.70	S
	SENSOR - TYRE PRESSU ?	1.0 EA	357.40			357.40	S

SERVICE ESTIMATE

80489 - C00001
Mr Tan Kian Meng
6 Pasir Ris View

SL: SERVICE SALES - PC

Singapore 518589

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Tan Kian Meng

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 9
Inv.date. : 30/03/2023
WIP No. . : 13473
Veh.In/Out:
*Tel.No. . : Mobile: 96714348
Reg.No. . : SFA606B
Reg.date . : 30/08/2019
Mileage .. : 0
Chassis No: SALWA2AU8KA871111

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	RH SHAFT - DRIVE ?	1.0	EA	3016.50			3,016.50	S
	FRAME CROSSMEMBER ?	1.0	EA	5309.80			5,309.80	S
	DISC - BRAKE ?	2.0	EA	827.90			1,655.80	S
	RH SHIELD - SPLASH ?	1.0	EA	277.00			277.00	S
	SENSOR - ABS ?	1.0	EA	196.40			196.40	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Done
Hf 9000008
17 days
31/03/23 @ 1610
Ready before print

Labour Total 52,576.00
Parts Total 133,452.00
Package Total 0.00

Gross Total. 186,028.00
Net..... 186,028.00
GST @ 8.0% 14,882.24
Total..... 200,910.25
Paid..... 0.00
Please Pay.. 200,910.25

GST: S=StdRated; O=OutOfScope; Z=ZeroRated; P=PreviousRate

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 964G

Vehicle Details

Vehicle No.: SFA606B
Vehicle to be Exported: No
Intended Deregistration Date: 27 Mar 2023
Vehicle Make: LAND ROVER
Vehicle Model: RANGE ROVER SPORT 3.0P (400PS)
Primary Colour: White
Manufacturing Year: 2019
Engine No.: 190426Z0041PT306
Chassis No.: SALWA2AU8KA871111
Maximum Power Output: 294.0 kW (394 bhp)
Open Market Value: \$89,190.00
Original Registration Date: 30 Aug 2019
First Registration Date: 30 Aug 2019
Transfer Count: 0
Actual ARF Paid: \$132,542.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Aug 2029
PARF Rebate Amount: \$99,406.00

Intended COE Rebate Details

COE Expiry Date: 29 Aug 2029
COE Category: E - Open - all except motorcycle
COE Period(Years): 10
QP Paid: \$40,002.00
COE Rebate Amount: \$24,790.00
Total Rebate Amount: \$124,196.00

The information contained herein is correct as at 27 Mar 2023

OK

Land Rover Range Rover Sport Mild Hybrid 3.0A

Overview

Insurance

Financial

Accessories

Similar

Research

Photos



HUI HUA CREDIT PTE LTD



Price	\$299,800		
Depreciation	\$34,890 /yr View models with similar depre	Reg Date	29-Nov-2019 (6yrs 7mths 26days COE left)
Mileage	69,500 km (20.8k /yr)	Manufactured	2019
Road Tax	\$2,382 /yr	Transmission	Auto
Dereg Value	\$127,434 as of today (change)	Fuel Type	Petrol-Electric
COE	\$39,700	OMV	\$90,357
Engine Cap	2,996 cc	ARF	\$134,643
Curb Weight	2,405 kg	Power	294.0 kW (394 bhp)