

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 65495 Page No. : 1 of 4
Date Estimated : 31/03/2023
Prepared By : Jack Ng Guo Ming

- ESTIMATE REPAIR FOR -
Bannak Mudiyanseilage Sandun Champik
16 Tanah Merah Kechil Link
#14-33

Singapore 465424

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SND6997Y	WBA12AK0907K41268	20/01/2022	218i Gran Coupe	7804

DESCRIPTION	VALUE
To remove and replace left wing mirror.	450.00
To check electrical wiring	177.00
To respray left wing mirror cap	74.00
Total Labour 1:	701.00

DESCRIPTION	QTY	PRIC	VALUE
LH OUTSIDE MIRROR HEATED WITH MEMOR	1	859.90	859.90
LH MIRROR GLASS HEATED WIDE ANDLE	1	435.90	435.90
LH OUTSIDE MIRROR COVER CAP PRIMED	1	133.90	133.90
Total Parts :			1,429.70



Labour 1	:	701.00
Parts	:	1,429.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	170.46
Grand Total	:	2,301.16

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **