## Automotive Repair Centre Pte Ltd CO. Reg. No.: 201312913C GST Reg. No.: 201312913C

**Estimate** 

38 Woodlands Industrial Park E1 #05-18, Singapore 757700 Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO.: EST2303-222 DATE: 31-Mar-2023

POLICY NO.: MSIG B 300613924 QMY

VEHICLE REG. NO.: SLH1678D

VEHICLE MAKE: HONDA CIVIC 1.5 TURBO CVT

TO Motor Claim Department Allianz Global Corporate & Specialty SE 12 Marina View, Asia Square Tower 2 Singapore 018961 Tel: 6297 2529

FOR SURVEYOR					

## **ESTIMATE REPAIR COST**

ESTIMATE REPAIR COST					
NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST	
	SPARE PARTS				
1	Rear Bumper	1	\$ 700.00	\$ 700.00	
2	Rear Bumper Clips	10	\$ 5.00	\$ 50.00	
3	Rear Bumper Retainer RH	1	\$ 40.00	\$ 40.00	
4	Rear Bumper Retainer LH	1	\$ 40.00	\$ 40.00	
5	Rear Reinforcement	1	\$ 400.00	\$ 400.00	
6	Rear Bumper Cover RH	1	\$ 40.00	\$ 40.00	
7	Rear Bumper Cover LH	1	\$ 40.00	\$ 40.00	
8	End Panel	1	\$ 440.00	\$ 440.00	
9	End Panel Top Garnish	1	\$ 80.00	\$ 80.00	
	Total Spare Parts				
	SPECIAL NETT				
10	Rear License Plate with Frame	1	\$ 35.00	\$ 35.00	
11	Rear Bumper Spoiler	1	\$ 180.00	\$ 180.00	
12	Reverse Sensor	1	\$ 250.00	\$ 250.00	
			Total Special Nett	\$ 465.00	
	<u>LABOUR</u>				
13	Spray painting Rear Bumper Including Blending	1	\$ 300.00	\$ 300.00	
14	Remove, Replace, Repair and Refit Affected Area	1	\$ 300.00	\$ 300.00	
15	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 100.00	\$ 100.00	
16	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00	
17	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00	
Estimate prepared by: Oscar Pong Total Labour					
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started.  Amount Before Excess					
Occasionally, worn or damaged parts are discovered which may not be evident on Add GST @ 7%					
the first inspection. Because of this, the above price are not guaranteed.					

the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Amount Payable \$ 3,343.75