



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23003450/Any3e2 Date: 19/06/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 7199J	Veh. Inspected	FBC 8776C
Policy No.	D-23100449MFCV/53	Coverage (\$)	0.00
Claim No.	D23001140MFCV	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	03/04/2023
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA T135	c.c	135
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	5YP300139	Colour	GREEN
Odometer	73874 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70/90 R17	MAXXIS	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	90/80 R17	MAXXIS	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/03/2023	Inspection Date	03/04/2023
Survey held at	JD MOTORSPORTS PTE LTD 25 KAKI BUKIT ROAD 4 #06-38 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	