



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23003553/Avy3e2	
			Date: 21/06/2023	
			Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJK 1908Z	Veh. Inspected	SNC 3600S
	Policy No.		Coverage (\$)	0.00
	Claim No.	BVS23/0259	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	05/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA AXIO HYBRID	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	NKE1657223120	Colour	BLACK
	Odometer	90637 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/50 R16	FALKEN	6 mm
	L/H Front Tyre	205/50 R16	FALKEN	6 mm
	R/H Rear Tyre	205/50 R16	FALKEN	6 mm
	L/H Rear Tyre	205/50 R16	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/04/2023	Inspection Date	04/04/2023
	Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks				
	A)REGISTRATION DATE: 15 OCT 2021 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	