

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

8% GST

Amount Amount

Amount

incld GST

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

: SQT23000988 : LONPAC INSURANCE BHD Document No. Page Customer 300 BEACH ROAD #17-04/07 Date : 1. Apr 2023 THE CONCOURSE **Customer No.** : WZL009 SINGAPORE 199555 Svc Advisor : ANIKKA LAI SWEE KAM : L15B71629356 **Registration No** : SLL1916X **Engine No** : 1. Apr 2023 12:03:31 PM Chassis No : MRHFC1660GT000464 Date | Time Model : CIVIC 1.5 TURBO VTIS YM2016 **Surveyor Name**

Owner's Name

Itom

: CHAY JUNFENG

Ins Policy No.

Date of Accident

: 30/3/2023

Description

Survey Date Authorisation Date

Unit Price Diec %

Otty

| Item | Description | Qty | Unit Price | Disc % | Amount | Amount | meia aa i |
|-----------------|---|-----------------|------------|-----------|---------|--------|-----------|
| | TP DIRECT SETTLEMENT (J/NO:) | | | | | | |
| | OWNER: CHAY JUNFENG | | | | | | |
| | OWNER INSURER: TOKIO MARINE | | | | | | |
| | ACC DATE: 30/03/2023 | | | | | | |
| | SURVEYED BY: | | | | | | |
| | DATE: | | | | | | |
| | REF NO: | | | | | | |
| | TP INSURER: LONPAC | | | | | | |
| | TP VEH: YM7773S | | | | | | |
| 71101-TEA-T00ZZ | FACEFR.BUMPER | 1 | 579.90 | 25 | 434.92 | 34.79 | 469.71 |
| 71198-TEA-T01 | SPACERL.FR.BUMPER SIDE | 1 | 10.40 | 25 | 7.80 | 0.62 | 8.42 |
| 91505-TM8-003 | CLIP,BUMPER | 10 | 2.30 | 25 | 17.25 | 1.38 | 18.63 |
| 71108-TEA-T10 | GARNISHL.FR.BUMPER SIDE | 1 | 16.50 | 25 | 12.37 | 0.99 | 13.36 |
| 71121-TEA-T02 | BASE,FR.GRILLE CHROME | 1 | 85.10 | 25 | 63.82 | 5.11 | 68,93 |
| 71125-TEA-T01 | MOLDINGFR.GRILLE | 1 | 115.80 | 25 | 86.85 | 6.95 | 93.80 |
| 71129-TEA-T01 | EXTENSION ASSYL.FR.GRILLE | 1 | 98.80 | 25 | 74.10 | 5.93 | 80.03 |
| 75700-TBA-A00 | EMBLEM | 1 | 17.40 | 25 | 13.05 | 1.04 | 14.09 |
| 74146-TEA-T00 | RUBBERHOOD SEAL | 1 | 31.80 | 25 | 23.85 | 1.91 | 25.76 |
| 33150-TEA-T11 | HEADLIGHT ASSYL. | 1 | 1373.00 | 25 | 1029.75 | 82.38 | 1112.13 |
| | | | | Sum Item | 1763.76 | 141.10 | 1,904.86 |
| BOSUN | SUNDRIES | 1 | 100.00 | | 100.00 | 8.00 | 108.00 |
| BML01I | INSPECT FR LIGHTING MECHANISMS & FOCUS | 1 | 160.00 | | 160.00 | 12.80 | 172.80 |
| BKBU01R | REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON | 1 | 1500.00 | | 1500.00 | 120.00 | 1620.00 |
| BP01R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (1P) | S. ₁ | 1200.00 | | 1200.00 | 96.00 | 1296.00 |
| | | | | Sum Labor | 2960.00 | 236.80 | 3,196.80 |
| | | | | | | | |

Printed on 1/4/2023 12:11:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53,50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co., Sdn., Bhd, it will be refunded,

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : LONPAC INSURANCE BHD

300 BEACH ROAD #17-04/07

THE CONCOURSE

SINGAPORE 199555

Registration No

: SLL1916X

Chassis No

: MRHFC1660GT000464

Model

: CIVIC 1.5 TURBO VTIS YM2016 : CHAY JUNFENG

Owner's Name

Ins Policy No. **Date of Accident**

: 30/3/2023

Description

Document No.

Date

: SQT23000988

: 1. Apr 2023

Customer No. Svc Advisor

: WZL009

: ANIKKA LAI SWEE KAM

Engine No

: L15B71629356

Date | Time

: 1. Apr 2023 12:03:31 PM

Surveyor Name

Survey Date

Authorisation Date

Unit Price

Total (Inclusive of GST)

8% GST Amount

Amount incld GST

Survey By Date & Time

Excess Status

Item

Signature

Total Amount

Disc %

4,723.76

377.90

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

Page

2

5,101.66

5,101.66

Printed on 1/4/2023 12:11:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.