



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD			Ref:	CS6/AIS23003486/Hwp3e2
79 ROBINSON ROAD			Date:	19/06/2023
#09-01 SINGAPORE 068897			Code:	AIS
1. Policy Particulars :- OWN DAMAGE (DESKTOP SURVEY)				
	Insured Veh.	Veh. Inspected	YQ 7144L	
	Policy No. SPCM1000000252	Coverage (\$)	0.00	
	Claim No. 202332006429	Excess (\$)	600.00	
	Assign From JANICE KOH	Assign Date	03/04/2023	
2. Vehicle Particulars & Condition				
	Make & Model	c.c	0	
	Engine No. HIDDEN	Year of Reg.	2022	
	Chassis No. JHHUCV3F10K044239	Colour		
	Odometer -	Steering		
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date 19/03/2023	Inspection Date		
	Survey held at 5 SOON LEE STREET #01-60 PIONEER POINT			
	Repairer CHENG AUTO BODYWORKS			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE)				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				