

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003321854	Date of Loss:	31/03/2023
Vehicle Reg. No.:	SLV2913U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM JING KAI		
Make/Model:	AUDI A4, 1.8 TFSI MU (EU6) (A)	Vehicle Reg. Date:	30/06/2014
Vehicle Colour:	BLACK	Chassis No:	WAUZZZ8K5EA119393
Engine No:	CJE077173		
Odometer:	157440 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	16,945.50
Miscellaneous Items	1,015.00
Labour	2,790.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	20,750.50
+ GST 8.00% (S\$)	1,660.04
Nett Amount (S\$)	22,410.54

This claim is handled by: THONG ZHONGMING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2023)
Parts: 143 AUDI A4 1.8 TFSI MU (EU6) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Wah Hong Motors & Credit Pte Ltd/SLV2913U/03/04/2023 14:44
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Headlamp LH <i>scu</i>	0.00	0.00	*1,200.00 F
2	1		*Headlamp lower bracket LH <i>?cm</i>	0.00	0.00	*90.00 F
3	1		*Front bumper <i>de</i>	0.00	0.00	*1,250.00 F
4	1		*Front bumper side retainer RH/LH @2*\$25 <i>nee</i>	0.00	0.00	*50.00 F
5	1		*Tower cover LH <i>XAA</i>	0.00	0.00	*35.00 F
6	1		*Front fender shield LH <i>de</i>	0.00	0.00	*140.00 F
7	1		*Front upper arm forward RH/LH @2*\$350 <i>?bt</i>	0.00	0.00	*700.00 F
8	1		*Front upper arm rear RH/LH @2*\$350 <i>?bt</i>	0.00	0.00	*700.00 F
9	1		*Front lower arm RH/LH @2*\$350 <i>?bt</i>	0.00	0.00	*700.00 F
10	1		*Front lower arm ball joint RH/LH @2*\$150 <i>?bt</i>	0.00	0.00	*300.00 F
11	1		*Front control arm RH/LH @2*\$650 <i>?bt</i>	0.00	0.00	*1,300.00 F
12	1		*Front absorber RH/LH @2*\$850 <i>?bt</i>	0.00	0.00	*1,700.00 F
13	1		*Front absorber bracket RH/LH @2*\$200 <i>?bt</i>	0.00	0.00	*400.00 F
14	1		*Front absorber top mounting RH/LH @2*\$70 <i>?de</i>	0.00	0.00	*140.00 F
15	1		*Front tie rod end RH/LH @2*\$120 <i>?bt</i>	0.00	0.00	*240.00 F
16	1		*Front rack end RH/LH @2*\$140 <i>?bt</i>	0.00	0.00	*280.00 F
17	1		*Front linkage RH/LH @2*\$120 <i>?bt</i>	0.00	0.00	*240.00 F
18	1		*Front anti roll bar bushing RH/LH @2*\$20 <i>?de</i>	0.00	0.00	*40.00 F
19	1		*Front fender RH/LH @2*\$550 <i>nee</i>	0.00	0.00	*1,100.00 F
20	1		*Front crossmember <i>?XAA</i>	0.00	0.00	*2,850.00 F
21	1		*Front anti roll bar <i>?XAA</i>	0.00	0.00	*340.00 F
22	1		*Fog lamp Cover RH/LH @2*\$85 <i>son</i>	0.00	0.00	*170.00 F
23	1		*Front fender LH <i>X repeated</i>	0.00	0.00	*550.00 F
24	1		*Lower engine front cover (front) <i>ton</i>	0.00	0.00	*450.00 F
25	1		*Lower engine front cover (Rear) <i>ton</i>	0.00	0.00	*440.00 F
26	1		*Front fender RH (Refer refer to labour)	0.00	0.00	*- F
27	1		*Bonnet (Refer refer to labour)	0.00	0.00	*- F

F=Franchise part.

Sub Total (\$\$)	11630	15,405.00
+ Margin on L,N Items 10.00% (\$\$)	10%	1,540.50
Total Parts (\$\$)	12733	16,945.50

Wah Hong Motors & Credit Pte Ltd/SLV2913U/03/04/2023 14:44. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	Engine lower cover clips <i>ny</i>		
2	1	Front bumper clip <i>nu</i>		
3	1	Front fender shield clip LH <i>n</i>		
4	1	Front rim LH 19 <i>su</i>		
			Sub Total (S\$)	1,015.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	800	1,000.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	800	1,000.00
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	80	60.00
4	To check and wheel computerize adjustment	New	60	80.00
5	Remove and replace front undercarriage RH/LH @2*\$200 <i>photo</i>	New	300	400.00
6	Remove and replace steering rack <i>photo</i>	New	100?	200.00
7	To remove and replace front rim LH and wheel balancing	New		50.00
			Gross Labour Cost (S\$)	2,790.00

Wah Hong Motors & Credit Pte Ltd/SLV2913U/03/04/2023 14:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12793

6688

495

2150

24126

209

19300.80

Repair limit

11K

Panel

Hp 90010068

8 days

L/S

04/04/23 @ 1430

EXCESS: 600

Repairer

Resy after repair

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 03 Aug 2023)**Parts:** 143 AUDI A4 1.8 TFSI MU (EU6) (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Wah Hong Motors & Credit Pte Ltd/SLV2913U/03/08/2023 11:59**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*Front bumper lower cover	CRA	0.00	0.00	*280.00 F ✓
2	1		*Front knuckle arm RH/LH@2*\$800	bt	0.00	0.00	*1,600.00 F ✓
3	1		*Front knuckle hub bearing RH/LH@2*\$400	bt	0.00	0.00	*800.00 F ✓
4	1		*Steering rack assy	CRA	0.00	0.00	*4,600.00 F ✓
Sub Total (S\$)							7,280.00
+ Margin on L,N Items 10.00% (S\$)							728.00
Total Parts (S\$)							8,008.00

F=Franchise part.

Wah Hong Motors & Credit Pte Ltd/SLV2913U/03/08/2023 11:59. Not valid without Reference section.

Generated using Merimen e-Claims IEAS