

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988**Our File No:** CS/EGI23003515/TWY3E2**Date:** 14/04/2023REFERENCE

Insured/Claimant:	GOH ZHI JUN MARCUS	Policy No:	DMG22006527
Date of Loss:	31/03/2023	Nature of Claim:	OD
		Claim No:	CDMPG23000795

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNA3263S</b>	Engine No:	HR12285847K
Make & Model:	NISSAN NOTE, 1.2 (A)	Chassis No:	JN1FAAE13Z0900157
Reg. Date:	17/06/2021 (Man. Year: 2021)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	S\$102,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R16	Rear Tyre Size:	185/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	04/04/2023	
Date Inspected:	05/04/2023	Inspected At: Tan Chong Motor Sales Pte Ltd (Bukit Timah) 911, Bukit Timah Road Singapore 589622
Estimated Period of Repair:	0.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$102,000.00
OMV :	\$21,694.00
PARF Rebate (1) :	\$5,529.00
Quota Premium Paid :	\$48,510.00
COE Rebate (2) :	\$39,751.00
Total Rebate (1) + (2) = :	\$45,280.00

The total amount incurred will be Market Value \$102,000.00 minus Total Rebate \$45,280.00 = \$56,720.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2023)
Parts:	144	NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA3263S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >