

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel Nc Fax No. : 62571330
 CO./ GST Reg. No. 201019626G
 SHD5023K

AAD2303-

Not Authorised
Putty B & paint

Vehicle No.:
 Chassis No.:
 Co UEN.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident:
 Third Party Insurer:
 Date of Registration:

03 APR 2023

SHD5023K
 JTDKB3FU303091326
 200303878K
 TOYOTA
 PRIUS GEN 4
 30/3/2023
 GBM130R/AIG
 21/8/2020

PART	LIST
1 COVER, FRONT BUMPER	\$ <i>Per</i> 659.40 <i>✓</i>
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$ <i>Per</i> 139.76 X
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ <i>Per</i> 902.16 X
1 ABSORBER, FRONT BUMPER ENERGY	\$ <i>Per</i> 100.91 X
1 SUPPORT, FRONT BUMPER SIDE, LH	\$ <i>Per</i> 100.49 <i>✓</i>
1 STAY SUB-ASSY, FRONT BUMPER, LH	\$ <i>Per</i> 59.85 X
1 MOULDING, FRONT BUMPER SIDE, LH	\$ <i>Per</i> 120.86 X
1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$ <i>Per</i> 624.54 X
1 RIM	\$ <i>Per</i> 1,995.11 X
1 FENDER SUB-ASSY, FRONT LH	\$ <i>Per</i> 1,236.69 <i>✓</i>
1 LINER, FRONT FENDER, LH	\$ <i>Per</i> 265.55 X
1 EMBLEM, SIDE PANEL, LH	\$ <i>Per</i> 68.88 <i>✓</i>
TOTAL	\$ 6,274.20
25%	\$ 1,568.55
	\$ 4,705.65

SPECIAL NETT	
1SET BUMPER CLIP FRT	\$ <i>Per</i> 65.00 <i>born</i>
1 FENDER LINER CLIP	\$ <i>Per</i> 65.00 X
1SET FRNT BUMPER RETAINER CLIP	\$ <i>Per</i> 85.00 X
TOTAL	\$ 215.00
TOTAL PARTS	\$ 4,920.65

LABOUR	
To rust-proofing of the affected areas.	\$ 600.00 <i>301</i>
Putty and spray painting of the affected portion.	\$ 1,200.00 <i>4401</i>

301 + 4401 = 4701
4701 + 215 = 4916
4916 + 1200 = 6116

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD5023K

AAD2303-

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 *400*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *na* 380.00 X

To check steering geometry and computer wheel alignment \$ *na* 220.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ *na* 170.00 X

TOTAL \$ 4,570.00

OVERALL TOTAL \$ 9,490.65

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: