

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6616D

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------------------|-------------------------|------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER | TO REPAIR SEE LABOUR | 459.40 | - |
| 1 | REAR BUMPER REINFORCEMENT | SERVICEABLE | 394.80 | - |
| 2 | REAR BUMPER REINFORCEMENT BRACKET RH/LH @ \$138.10 | SERVICEABLE | 276.20 | - |
| 1 | REAR BUMPER CENTRE MOULDING | DEFORMED | 451.25 | 451.25 |
| 10 | REAR BUMPER CLIPS @\$2.20 | NOT NECESSARY | 22.00 | - |
| 1 | REAR BUMPER REFLECTOR LAMP LH | SERVICEABLE | 41.45 | - |
| 1 | REAR BUMPER TOW COVER | SCRATCHED | 98.80 | 98.80 |
| 1 | REAR BUMPER FOGLAMP | SCRATCHED | 201.50 | 201.50 |
| 1 | REAR SMART KEY ANTENNA | SERVICEABLE | 40.50 | - |
| | LESS 20% DISCOUNT | | -397.18 | -150.31 |
| | | | 1,588.72 | 601.24 |
| | NETT ITEMS | | | |
| 1 | REVERSE SENSORS (N) | NOT WORKING | 180.00 | 180.00 |
| 1 | REAR NO.PLATE WITH TRIM COVER (N) | CRACKED | 55.00 | 55.00 |
| | LESS 10% DISCOUNT | | -23.50 | -23.50 |
| | | | 211.50 | 211.50 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER. | | 400.00 | 350.00 |
| | SPRAY PAINTING CHARGE. | | 300.00 | 250.00 |
| | REMOVE/REFIX REVERSE SENSOR. | | 120.00 | 30.00 |
| | | | 820.00 | 630.00 |
| | GRAND TOTAL | | 2,620.22 | 1,442.74 |





Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 1,150.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | |
| (CONFIRMED) | | |

Report Ref No. NS/INC23003525/Nqy3m4

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

` '

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser