

Shiau Chan (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Tuesday, 6 June 2023 2:54 PM
To: Shiau Chan (LKKAuto)
Subject: Re: NTUC-TP SH 9185Z SURVEYED BY NAZ (OUR REF: NS/INC23003528/Nqp3)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SH9185Z, FOUND NO PARF/COR REBATE PRINT OUT UPLOAD & NOT ECONOMICAL TO REPAIR.

Best Regards,

Simon Ho
LKK Auto Consultants Pte Ltd
Phone: 6256-3561| email: simonho@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Tuesday, 6 June 2023 11:49 am
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: NTUC-TP SH 9185Z SURVEYED BY NAZ (OUR REF: NS/INC23003528/Nqp3)

Dear Simon,

For your audit.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)