

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305550430
Date : 10.04.2023

FINALIZATION FORM

To : LKK

Attn : NAZ

Vehicle Reg No. : SHC7516Y

Date of Accident : 31.03.2023

Fax :

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME --- FBU 527M

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges (include advertisement stickers etc, if any)

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

~~\$4,200.00~~ \$3,500.00
~~\$4,200.00~~ \$3,500.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : NAZ

Date : 26/4/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee / GEARS	\$26.75 / \$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK -

DATE: 03.04.2023

FBU 527M

MODEL: Toyota Prius

INSURANCE: INCOME (45)

VEHICLE NO.: SHC7516Y - CityCab

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1	CR A	\$503.04
	Rear Bumper Side Retainer RH	1		\$112.70
	Rear Bumper Clips	10	\$2.20	\$22.00
	Rear Bumper Lower Extension RH	1		\$232.00
	Rear Fender RH	1		\$992.04
	Rear Wheel Rim RH	1		\$1,570.55
	Rear Door RH	1		\$1,264.00
	SUB TOTAL		2,653.49	\$4,696.33
	LESS 25%			\$1,174.08
	DISCOUNTED PARTS TOTAL		1,950.12	\$3,522.25
	Rear Door ZIG Apps RH	1		\$80.00
	S/NETT LESS 10%			\$8.00
	S/NETT TOTAL			\$72.00
	Rear Door Adv.Sticker RH	1		\$100.00
	Rear Fender Adv.Sticker RH / LH	2		\$200.00
	Rear Bumper Adv.Sticker	1		\$50.00
	Rocker Panel Garnish Adv.Sticker RH	1		\$100.00
	NETT TOTAL			\$450.00
	SPARE PARTS TOTAL			\$4,044.25
	<u>Labour Charge</u>			
	Panel Beating			\$1,200.00
	Spray Painting Charge - Rocker Panel Garnish RH etc			\$1,200.00
	Tuff Kote			\$40.00
	Remove/Refix Reverse Sensor			\$120.00
	TOTAL LABOUR		4,382.1175	\$2,560.00
	ESTIMATE TOTAL			\$6,604.25

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Plans prices are subject to confirmation

Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

NAR LKK
3/4/2023 1615
LIS
3 DMS
CHECK ITEM (HOTO)
MTEL 06 PMR (HOTO)



VEHICLE	:	<u>SHC7516Y</u>	TYPE OF CLAIM :	<u>TP</u>
MODEL	:	<u>TOYOTA PRIUS</u>	SURVEYED BY :	<u>LKK - NAZ</u>
JOB NO	:	<u>305550430</u>	DATE	<u>20.03.2023</u>

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]