LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way

#09-16

Singapore 079120

LKK Auto Consultants Pte Ltd From:

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 05 Apr 2023

Preliminary Advice

Vehicle No : SNJ8018D Accident Date : 07/03/2023 Make : AUDI E-TRON Policy No. : 7220122529 Assignment Date : 05/04/2023 **Excess** : S\$0.00 Date of Inspection : 4/4/2023 Est. Duration of Repair : 3

Inspection At : PREMIUM AUTOMOBILES PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,624.00
Revised Amount	:S\$	19,177.00
Check Items (Estimated)	:S\$	1,125.00
Total	:S\$	20,302.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 300,000.00 COE / PARF Rebate :S\$ 136,815.00

Salvage Value :S\$

Margin for Repair :S\$ 163,185.00.

Remarks

(X)	The vehicle is repairable at our	adjusted amount	. We have a	also confirmed	excess an	nd policy	coverage.	Kindly	let
	us have your authorisation.								

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.