

City Auto Pte Ltd (Co.Reg.No:199503435C)160 Sin Ming Drive #05-01,, Sin Ming AutoCity,
Singapore 575722

Tel: 6453 1235 Fax: 6453 7944 Email: jason@cityauto.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	AIS/2022/0000394/000147	Date of Loss:	31/03/2023
Vehicle Reg. No.:	YQ8959X	Driveable?	
Driver Age/Info:	56 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHARISSPEED INTERNATIONAL		
Driver:	LEE CHUAN LEONG VINCENT		
Make/Model:	HINO XZU710R, 4.0 D 14FT WIDE CAB 5T (M)	Vehicle Reg. Date:	30/11/2022
Vehicle Colour:	WHITE		
Engine No:	N04CWN20660	Chassis No:	JHHUCV3F80K047655
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6.5		

Present Location: **CITY AUTO PTE LTD (HQ)****COST OF CLAIMS**

	Amount
Parts	2,607.00
Miscellaneous Items	25.00
Labour	1,350.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	3,982.00
- Excess (S\$)	600.00
(S\$)	3,382.00
+ GST 8.00% (S\$)	270.56
Nett Amount (S\$)	3,652.56

This claim is handled by: **VRONICA**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 04 Apr 2023)**Parts:** N/A HINO XZU710R 4.0 D 14FT WIDE CAB 5T (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** City Auto Pte Ltd/YQ8959X/04/04/2023 14:01**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front panel	0.00	0.00	*350.00 F, Buc
2	1		*Front grille	0.00	0.00	*250.00 F, DT
3	1		*Front grille emblem	0.00	0.00	*75.00 F, MHS
4	1		*Front bumper	0.00	0.00	*250.00 F, ?
5	1		*Front bumper reinforcement	0.00	0.00	*280.00 F, ?
6	2		*Front bumper bracket	0.00	0.00	*370.00 F, ?
7	1		*RH headlamp	0.00	0.00	*550.00 F, CRA
8	1		*RH foglamp	0.00	0.00	*115.00 F, ?
9	1		*Hino emblem	0.00	0.00	*65.00 F, NEC
10	1		*300 emblem	0.00	0.00	*65.00 F, NEC

F=Franchise part.

Sub Total (S\$)	2,370.00
+ Margin on L,N Items 10.00% (S\$)	237.00
Total Parts (S\$)	2,607.00

City Auto Pte Ltd/YQ8959X/04/04/2023 14:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Number plate	25.00 <i>BT</i>
Sub Total (\$\$)			25.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	New	600.00 500
2	- Spray painting on affected and replace parts	New	600 750.00
Gross Labour Cost (\$\$)			1,350.00

City Auto Pte Ltd/YQ8959X/04/04/2023 14:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 5 DAYS

- NOT AUTHORISE
- EXCESS \$ 600
- P/P OR H/S REPAIR?
- SURVEY BY EDWARD TEL 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: