

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI23003358/Uqy3q2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Date:	03/05/2023	
			Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJK 9519K	Veh. Inspected	SLE 8635Y	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10021345/KR	Excess (\$)	0.00	
	Assign From	DON BONG	Assign Date	05/04/2023	
2.	2. Vehicle Particulars & Condition				
	Make & Model	SUZUKI SWIFT	c.c	1372	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JSAFZC82S00332896	Colour	SILVER	
	Odometer	147782 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	185/55 R16	DUNLOP	6 mm	
	L/H Front Tyre	185/55 R16	DUNLOP	6 mm	
	R/H Rear Tyre	185/55 R16	DUNLOP	6 mm	
	L/H Rear Tyre	185/55 R16	DUNLOP	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT MIRROR.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	20/03/2023	Inspection Date	11/04/2023	
	Survey held at	PRECISE AUTO SERVICE			
		NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

1 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: