

# CHEONG CHEONG MOTOR SERVICE PTE LTD

BLK 5032 ANG MO KIO IND. PARK 2 #01-293 SINGAPORE 569535

TEL : 6481 4152 FAX : 6481 4157

e-mail : c2msvc@singnet.com.sg

Our Ref : 081/04/2023

Page : 1

Date : 05/04/2023

M/S : AUTO & GENERAL INSURANCE SINGAPORE PL  
190 CLEMENCEAN AVE #03-01  
SINGAPORE SHOPPING CENTRE  
SINGAPORE 239924

ACCIDENT REPAIR ON : GBF 9601 B - TOYOTA DYNA 150  
CHASSIS NO :  
DATE OF ACCIDENT : 04/04/2023

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED :-

## REPLACEMENT OF PARTS

- 1 TAILGATE
- 2 REAR STICKER "TOYOTA"
- 3 END PANEL 495.10
- 4 REVERSE SENSOR
- 5 SPARE TYRE BRACKET
- 6 TAILAMP LEFT
- 7 TAILAMP RIGHT
- 8 REAR NUMBER PLATE
- 9 REAR NUMBER PLATE BRACKET
- 10 REAR SUSPENSION LEFT
- 11 REAR SUSPENSION RIGHT
- 12 COIN SPRING BRACKET LEFT
- 13 COIN SPRING BRACKET RIGHT
- 14 REAR EXHAUST PIPE
- 15 REAR EXHAUST BOX

|        | B1 | S\$      |          | S\$    |
|--------|----|----------|----------|--------|
|        | B1 | 1,057.23 |          |        |
|        | m  | 80.00    |          |        |
|        | B1 | 987.50   |          |        |
| S/NETT |    |          | 250.00   | 200.00 |
|        | m  | 165.40   |          |        |
|        | cm | 253.20   |          |        |
|        | m  | 253.20   |          |        |
| S/NETT |    |          | 20.00    |        |
| S/NETT |    |          | 124.50   |        |
|        | B1 | 282.00   |          |        |
|        | B1 | 282.00   |          |        |
|        | B1 | 160.00   |          |        |
|        | B1 | 160.00   |          |        |
|        | B1 | 187.00   |          |        |
|        | B1 | 486.50   |          |        |
|        |    | 4,354.03 |          |        |
|        |    | 435.40   |          |        |
|        |    |          | 3,918.63 |        |
|        |    |          | 4,313.13 |        |

## ABOUT CHARGES :

- 16 STRIP / REFIT UNDERCARRIAGE ACCESSORIES
- 17 KNOCKING PUSH OUT REAR ACCIDENT PARTS CUT & WELD END PANEL STRIP / REFIT ABOVE ACCESSORIES
- 18 SPRAY PAINT & ANTI-TUFF-KOTE ON REAR ACCIDENT DAMAGE AREAS

300.00 200  
1,100.00 600  
950.00 550  
6,663.13

