



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref:	CS3/SMO22006468/Uwp3e2-1
50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Date:	11/04/2023
			Code:	SMO
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLF 5631Y	Veh. Inspected	SMJ 2603R
	Policy No.	D21MTPV01010807	Coverage (\$)	0.00
	Claim No.	CMTD2202303/MYE	Excess (\$)	0.00
	Assign From	AGNES CHAN	Assign Date	31/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ACCENT (A)	c.c	1368
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KMHCU41BTKU464993	Colour	PINK
	Odometer	65598 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/50 R16	BRIDGESTONE	7 mm
	L/H Front Tyre	195/50 R16	BRIDGESTONE	7 mm
	R/H Rear Tyre	195/50 R16	BRIDGESTONE	7 mm
	L/H Rear Tyre	195/50 R16	BRIDGESTONE	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/07/2022	Inspection Date	06/07/2022
	Survey held at	SV AUTOWORKS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	