

Repair Estimate


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HONDA VEZEL
 Engine/Chassis No.: RU31115842
 Date of accident: 04.04.23
 Damaged area: O/S

Date: 10/04/2023
 Claim Type: TP
 VRN: SLD1406T



Not Authorized
11/04/2023 8:1800p
Running After Rain
3 days

List Items					
S/N	Parts description		QTY	UNIT PRICE	AMOUNT
1	Front fender o/s	386	1/1	1	\$ 882.00 \$ 882.00
2	Front fender cowling o/s		SL	1	\$ 185.00 \$ 185.00
3	Front fender splash guard o/s		SL	1	\$ 76.00 \$ 76.00
4	Front bumper		SL	1	\$ 976.00 \$ 976.00
5	Front bumper retainer		SL	2	\$ 85.00 \$ 170.00
6	Wing mirror o/s	} 850	130	1	\$ 653.00 \$ 653.00
7	Wing mirror outer cover o/s		1/1	1	\$ 172.00 \$ 172.00
8	Wing mirror signal lamp o/s		1/1	1	\$ 195.00 \$ 195.00
9	Wing mirror glass o/s		1/1	1	\$ 116.00 \$ 116.00
10	Front fender arch garnish o/s		SL	1	\$ 357.00 \$ 357.00
Subtotal					\$ 3,782.00
List discount					20.00%
Total					\$ 3,025.60

Special nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Front fender cowlings clips o/s <i>NN</i>	8	\$ 5.50	\$ 44.00	X
2	Front bumper clips <i>NN</i>	10	\$ 5.50	\$ 55.00	X
3	Front fender arch garnish clips o/s <i>NN</i>	8	\$ 5.50	\$ 44.00	X
4	Sundries <i>NN</i>	1	\$ 50.00	\$ 50.00	X
Total				\$ 193.00	

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00 <i>3001</i>
2	To disconnect wire harness and electrical component to facilitate repairs, reconnect and check functions.	0.25	\$ 50.00 <i>201</i>
3	To undercoat all affected portions after repair.	1	\$ 200.00 <i>301</i>
4	Supply spray paint material and necessary items to respray affected area / panel.	4	\$ 800.00 <i>2801</i>
Total labour			\$ 2,050.00
Estimate Grand Total			\$ 5,268.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date:
Signature:

Acknowledged by Repairer

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company