

Our Job Ref No : 305550781

Date 10.04.23

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. SHC174U

Date of Accident : 05.04.23

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to : INCOME --- SHD1134A
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \_\_\_\_\_
  - (b) Labour Charges \_\_\_\_\_
  - Total for Part-By-Part Repair Cost** \_\_\_\_\_
  - (c) Lumpsum Repair (if applicable)
  - Total for Lumpsum repair cost after Less: 20% \$1,200.00
  - Final Lumpsum Repair cost** \_\_\_\_\_

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
 Name : JUMANI  
 Tel : 62148315  
 Fax : 65468156

Signature :   
 Name : NAZ  
 Date : 21/4/2023

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	26.75/2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

\_\_\_\_\_

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO **SHC1744U**  
 MAKE **HYUNDAI**  
 MODEL **IONIQ**

DATE: **05.04.23**  
 MVA **JUMANI**  
 DOA: **05.04.23**

*INCOME*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY ✓ CRA			\$459.40
1	REAR BUMPER CENTRE MOULDING ✓ CRA			\$451.25
1	REAR BUMPER BEAM ? X SUC			\$394.80
10	REAR BUMPER CLIPS ✓ NPL			\$22.00
1	FOG LAMP REAR X SUC			\$201.50
1	ANTENNA SMARTKEY X SUC			\$40.50
<b>SUB TOTAL</b>				<b>\$1,569.45</b>
<b>LESS 20%</b>				<b>\$313.89</b>
<b>DISCOUNTED TOTAL</b>				<b>\$1,255.56</b>
	REAR NUMBER PLATE ✓ CRA			\$50.00
	REVERSE SENSOR X SUC			\$180.00
	REAR BUMPER MAT ✓ NPL			\$50.00
<b>Labour Charge</b>				<b>\$280.00</b>
	PANEL BEATING			350 \$400.00
	SPRAY PAINT			250 \$300.00
	REMOVE / REFIX REVERSE SENSOR			30 \$50.00
<b>TOTAL LABOUR</b>				<b>\$750.00</b>
<b>ESTIMATE TOTAL</b>				<b>\$2,285.56</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

NET  
NET

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*NAZ LKK  
 6/4/2023 1605  
 LIS  
 2 DAYS  
 CHECK ITEM PHOTOS / AFTER REPAIR PHOTOS*