



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR YN7194H*4C-E

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No 16319
Reg No/Reg Date YN7194H*4C-EO/ 23/12/2014
Date In/Mileage / 335297
Chassis No WDB9066532S921652
Engine No 65195520414461
Make/Model MBCV/516CDI/3665 Spr
Colour/Trim 595 Vanda Blue / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	06/04/2023/ 14:53	PC	610 / Philip Cheong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A 00940101 TO REMOVE & REPAIR SIDE PANEL AND SLIDING DOOR @900x4				3600 5040.00
A 00940101 TO PUTTY & SPRAY PAINTING @900x3				2700 3600.00
A 00940101 LOGO				2000 3600.00
A 00940101 TO REMOVE & REFIT REAR INNER SECURITY VAULT BRACKET photo? 900x3				2700 3600.00
M EDGE GUARD SECTION	1.00	17.31	00.00	17.31
M SIDEWALL PANELING photo?	1.00	1181.01	00.00	1181.01
M MOULDING	1.00	272.61	00.00	272.61
M PROTECTIVE STRIP	1.00	239.53	00.00	239.53
M SEAL	1.00	204.00	00.00	204.00
M SIDE DOOR photo?	1.00	3278.68	00.00	3278.68
M DOOR SLIDE MECHANISM	1.00	214.81	00.00	214.81
M DOOR HANDLE	1.00	53.09	00.00	53.09
M DOOR SLIDE MECHANISM	2.00	0.00	00.00	
M BEARING CLAMP	1.00	117.36	00.00	117.36
M PAD - 40	1.00	2.42	00.00	2.42

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

Nett 21,420.82
8% GST on 21420.82 1713.67

Authorized signatory and company stamp

Total Payable 23,134.49

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Gardens MBCV Customer Service Center
209 Pandan Gardens
Singapore 609339
Tel: 6771 4389
Fax: 6775 6310
www.mercedes-benz.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	601N
Vehicle No.:	YN7194H
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Apr 2023
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	SPRINTER 516CDI 3665 HIGH ROOF A/T ABS
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	651955414461
Chassis No.:	WDB90665325921652
Maximum Power Output:	-
Open Market Value:	\$55,273.00
Original Registration Date:	23 Dec 2014
First Registration Date:	23 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$2,764.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	22 Dec 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$61,000.00
COE Rebate Amount:	\$10,511.00
Total Rebate Amount:	\$10,511.00

The information contained herein is correct as at 13 Apr 2023

OK