

**SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705  
FAX Number : 63665592  
Estimator Telephone Number : 68662623  
Accident Reporting Number : 68662672

Date Generated : 10/04/2023  
User ID : BoonChewTay

**Section A - Accident Details**

Registration Number	9HB1222P
Case Reference Number	TAX/04/23/2016
Registration Date	16/9/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	CHAN KOK SENG
Type of Accident	Head to Rear
Accident Date and Time	6/4/2023 5:05 PM
Accident Reported Date and Time	8/4/2023 8:22 AM
Insurance Surveyor Required?	No
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118128
Special Instruction to ARC, if any	REAR PORTION
Prepared Date and Time	10/4/2023 11:32 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,200.00	\$0.00
Total Spray Cost	\$658.00	\$0.00
Total Spare Part Cost	\$2,670.53	\$0.00
Total Other Cost	\$1,000.00	\$0.00
<b>TOTAL COST</b>	<b>\$5,528.53</b>	<b>\$0.00</b>
Ump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	2 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	10/04/2023 11:44 AM	
Signature		
Remarks		

**Section C - Quotation and Accident Invoice Details**

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Quotation Amount		Prepared Date	

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Part's prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
 60 Woodlands Industrial Park E4, Singapore 757705  
 FAX Number : 63685592  
 Estimator Telephone Number : 68662623  
 Accident Reporting Number : 68662672

Date Generated : 10/04/2023

User ID : BoonChewTay

## Section D - Details of Repair Estimates

Part 1 - Labour Works	Quotation from AR	Adjusted by Surveyor, if applicable
Job Scope	\$1,200.00	4001
REPAIR REAR PORTION	\$1,200.00	

Part 2 - Spray Painting & Panel Beating Related Works	Quotation from ARC	Adjusted by Surveyor, if applicable
Job Scope	\$428.00	2301
RESPRAY REAR BUMPER	\$230.00	~ X
RESPRAY REAR PANEL	\$658.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense	Quotation from ARC	Adjusted by Surveyor, if applicable
Job Scope	\$60.00	~ X
WASH AND VACUUM	\$120.00	201
CHECK WIRING AND SYSTEM FUNCTION	\$100.00	~ X
APPLY RUST-PROOFING ON AFFECTED AREA	\$120.00	601
TEST AND REFIX REVERSE SENSOR SYSTEM	\$100.00	~ X
REPLACE SUNDRY PARTS	\$350.00	?
CHECK & RESET SYSTEM FUNCTION	\$150.00	?
TOTAL OF (EV) (NET)	\$1,000.00	

Spare Parts / Material Usage									
Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10395721-SEPP	PANEL ASM-RR END	1.00	\$708.66	10.00	\$637.79	Replace	?
		10369261-SPRP	FASCIA-RR BPR	1.00	\$758.48	10.00	\$682.63	Replace	Beu ✓
		10751490	FASCIA-RR BPR LWR	1.00	\$230.68	10.00	\$207.61	Replace	Beu ✓
		10359003	FINISHER-RR BPR - RH	1.00	\$47.42	10.00	\$42.68	Replace	CM ✓
		10465727	BRACKET-RR BPR FASCIA SI-RH	1.00	\$29.85	10.00	\$26.87	Replace	?
		10328371	BRACKET-RR BPR FASCIA SI MTG - RH	1.00	\$46.08	10.00	\$41.47	Replace	?
		10371790	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - RH	1.00	\$12.90	10.00	\$11.61	Replace	?
		90003417	SCRIVET-RR BPR FASCIA	2.00	\$0.84	10.00	\$1.51	Replace	Beu ✓
		10327894	BAR ASM-RR BPR IMP	1.00	\$339.77	10.00	\$305.79	Replace	?
		10587412	LAMP ASM-TAIL(LID SI) - RH	1.00	\$407.68	10.00	\$366.91	Replace	(CM) N.C X
		10726677	LAMP ASM-RR FOG - RH	1.00	\$189.07	10.00	\$170.16	Replace	CM ✓
		10376550-WSD	SENSOR-RR PARK DIST CONT	3.00	\$65.00	10.00	\$175.50	Replace	Beu X
					<b>\$2,836.43</b>		<b>\$2,870.53</b>		

Spare Parts / Material Usage After Surveyor Signed off									
Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check