

Huey Yon (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Friday, 21 April 2023 1:13 PM
To: Huey Yon (LKKAUTO)
Subject: Re: AIS-PRS / SLD 3191Z -SURVEY BY Akid (CS3/AIS23003672/Wnp3)

Dear Huey Yon,

AUDIT CHECK DONE FOR SLD3191Z, FOUND MV CALCULATION ERROR, MV SHOULD BE \$59K & REPAIR DAY NEEDED SHOULD BE 5 DAYS.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Huey Yon (LKKAUTO) <hueyyon@lkkauto.com>
Sent: Friday, 21 April 2023 11:32 am
To: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Subject: AIS-PRS / SLD 3191Z -SURVEY BY Akid (CS3/AIS23003672/Wnp3)

Dear Simon,

For your audit.

Best Regards,

Huey Yon | case handler

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933