



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref: CS/CTI23003710/Aqp3	
3 ANSON ROAD #16-00		Date: 11/04/2023	
SPRINGLEAF TOWERSINGAPORE 079909		Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YM 6778K	Veh. Inspected	SLC 3997X
Policy No.	DMCVSNW00056392200	Coverage (\$)	0.00
Claim No.	SNM23D202560/C02	Excess (\$)	0.00
Assign From	CECILIA LEE	Assign Date	10/04/2023
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/04/2023	Inspection Date	11/04/2023
Survey held at	HIAP HONG MOTOR REPAIR 2 KAKI BUKIT AVE 2 #02-13 SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			