



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref:	CS3/SMO22012162/Uny3e2-1
50 RAFFLES PLACE #03-03		Date:	13/04/2023
SINGAPORE LAND TOWERSINGAPORE 048623		Code:	SMO
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLN 9494H	Veh. Inspected	SMY 8552K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2204428/SYH	Excess (\$)	0.00
Assign From	HWANG SHIANG YI	Assign Date	11/04/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA CIVIC (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JHMF4620AS200152	Colour	BROWN
Odometer	98872 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/45 R17	HABILEAD	6 mm
L/H Front Tyre	215/45 R17	HABILEAD	6 mm
R/H Rear Tyre	215/45 R17	GITI	6 mm
L/H Rear Tyre	215/45 R17	GITI	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.			
DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	03/12/2022	Inspection Date	06/12/2022
Survey held at	SHIFTER AUTO GARAGE PTE LTD 3016 BEDOK NORTH AVENUE 4 #07-04 EASTECH SINGAPORE 489947		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	