

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 202332006652 Date: 19th May 2023

Our Ref: CS6/AIS23003730/Kwp3m4

M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01 Singapore 068897

Dear Sir / Madam,

DESKTOP SURVEY OF ACCIDENT VEHICLE SLC 9194G ACCIDENT ON 21/03/2023

We thank you for your instruction on 11/04/2023.

The following vehicle information was recorded:

Registration Number : SLC 9194G

Make & Model : M.G. HS 1.5T AT Chassis Number : LSJA24U90MN024708

Year of Registration : 2021 Engine Capacity : 1490 cc

- 1. The vehicle sustained damages at the front n/s portion. (Details see photographs enclosed)
- 2. We recommend that the repairs of the entire damage require about <u>2 (Two)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.