



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD
79, ROBINSON ROAD #09-01
SINGAPORE 068897

ESTIMATE

NO : QUOT202304-000023(00)
DATE : 28/04/2023
POLICY NO : SP2003907937
VEH REG NO : SNG7311D
MAKE/MODEL : MERCEDES BENZ E200 SEDAN
AVG (R18 LED)
CHASSIS NO : WDD2130802A672697
ENGINE NO : 26492080001492
REG. DATE : 2019

ATTN : MOTOR CLAIMS DEPT
TEL : FAX :

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 23/03/2023

Estimate Repair Cost to Vehicle No : SNG7311D

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Side skirt - RH	1	520.00 (Pd)	520.00 ✓
2 Side skirt clips - RH	16	8.00 (Mn)	128.00 ✓
			648.00
		Add 10%	64.80
			712.80
		TOTAL	S\$ 712.80
		ADD GST @ 8%	57.02
		GRAND TOTAL	S\$ 769.82

SINGAPORE DOLLAR SEVEN HUNDRED SIXTY-NINE AND CENTS EIGHTY-TWO ONLY

Parts: \$ 3,018.40
 SN : 60.00
 labour : 1,030.00
 Supp : 648.00

 \$ 4,756.40
 XS 700.00

 \$ 4,056.40
 8% 324.51

 \$ 4,380.91

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE