





# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01  
SINGAPORE 068897

*Not Authorized  
Recovery B4 paint*

ATTN : MOTOR CLAIMS DEPT

TEL :

FAX :

*Ex TBA*

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 23/03/2023

*4 days  
\$ 4756.40*

## ESTIMATE

NO : QUOT202304-000023(00)

DATE : 11/04/2023

POLICY NO : SP2003907937

VEH REG NO : SNG7311D

MAKE/MODEL : MERCEDES BENZ E200 SEDAN  
AVG (R18 LED)

CHASSIS NO : WDD2130802A672697

ENGINE NO : 26492080001492

REG. DATE : 2019

### Estimate Repair Cost to Vehicle No : SNG7311D

Description	Quantity	Unit Price	Amount	
			S\$	S\$
<b>PARTS</b>				
1 Front door - RH	1	1,450.00	<i>R1</i>	1,450.00 ✓
2 Front door weatherstrip - RH	1	238.00	<i>M2</i>	238.00 ✓
3 Front door trimboard rivets - RH	20	12.00	<i>M2</i>	240.00 ✓
4 Front door hinges - RH	2	125.00	<i>R1</i>	250.00 ✓
5 Front door lower seal	1	48.00	<i>D1/1</i>	48.00 ✓
6 Front fender - RH	1	720.00	<i>R1</i>	720.00 ✓
7 Front fender vertical garnish - RH	1	38.00	<i>Dal/67</i>	38.00 ✓
				2,984.00
			Add 10%	298.40
				3,282.40
<b>LABOUR</b>				
8 To transfer RH front damaged door interior mechanism and glass to new door	1	150.00		150.00 <i>601</i>
9 To check and rectify wiring system	1	80.00		80.00 <i>201</i>
10 To panel beat & straighten RH front door pillar, RH front fender inner panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00		1,000.00 <i>400</i>
11 To putty and spray paint on affected areas	1	1,000.00		1,000.00 <i>5501</i>
				2,230.00
			TOTAL	S\$ 5,512.40
			ADD GST @ 8%	440.99
			GRAND TOTAL	S\$ 5,953.39

SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED FIFTY-THREE AND CENTS THIRTY-NINE ONLY

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

*Kn*

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD  
79, ROBINSON ROAD #09-01  
SINGAPORE 068897

### ESTIMATE

NO : QUOT202304-000023(00)  
DATE : 11/04/2023  
POLICY NO : SP2003907937  
VEH REG NO : SNG7311D  
MAKE/MODEL : MERCEDES BENZ E200 SEDAN  
AVG (R18 LED)  
CHASSIS NO : WDD2130802A872697  
ENGINE NO : 26492080001492  
REG. DATE : 2019

ATTN : MOTOR CLAIMS DEPT

TEL :

FAX :

*Ex TBA*

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 23/03/2023

*Not within  
Policy B&paint  
12/4/23 4 days  
S*

### Estimate Repair Cost to Vehicle No : SNG7311D

Description	Quantity	Unit Price	Amount
		S\$	S\$
<b>PARTS</b>			
1 Front door - RH	1	1,450.00	1,450.00 ✓
2 Front door weatherstrip - RH	1	238.00	238.00 ✓
3 Front door trimboard rivets - RH	20	60SN 12.00	<del>240.00</del> ✓
4 Front door hinges - RH	2	125.00	250.00 ✓
5 Front door lower seal	1	48.00	48.00 ✓
6 Front fender - RH	1	720.00	720.00 ✓
7 Front fender vertical garnish - RH	1	38.00	38.00 ✓
			2,984.00
		Add 10%	298.40
			3,282.40 <i>60SN</i>
<b>LABOUR</b>			
8 To transfer RH front damaged door interior mechanism and glass to new door	1	150.00	150.00 <i>60L</i>
9 To check and rectify wiring system	1	80.00	80.00 <i>20L</i>
10 To panel beat & straighten RH front door pillar, RH front fender inner panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 <i>400L</i>
11 To putty and spray paint on affected areas <i>Side skirt</i>	1	1,000.00	<del>1,000.00</del> <i>440L 440L</i>
			2,230.00 <i>1030</i>
		TOTAL	S\$ 5,512.40
		ADD GST @ 8%	440.99
		GRAND TOTAL	S\$ 5,953.39

*10% \$ 2,744.00  
\$ 274.40  
\$ 3,018.40*

*NOT consistent*

SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED FIFTY-THREE AND CENTS THIRTY-NINE ONLY

*23998.40*

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD  
79, ROBINSON ROAD #09-01  
SINGAPORE 068897

## ESTIMATE

NO : QUOT202304-000023(00)  
DATE : 28/04/2023  
POLICY NO : SP2003907937  
VEH REG NO : SNG7311D  
MAKE/MODEL : MERCEDES BENZ E200 SEDAN  
AVG (R18 LED)  
CHASSIS NO : WDD2130802A672697  
ENGINE NO : 26492080001492  
REG. DATE : 2019

ATTN : MOTOR CLAIMS DEPT

TEL : FAX :

YOUR REF NO :  
CLAIM TYPE : OWN DAMAGE  
ACCIDENT DATE : 23/03/2023

### Estimate Repair Cost to Vehicle No : SNG7311D

Description	Quantity	Unit Price	Amount
		S\$	S\$
<b>SUPPLEMENTARY PARTS</b>			
1 Side skirt - RH	1	<i>Nd</i> 520.00 <i>(Nd)</i>	520.00 ✓
2 Side skirt clips - RH	16	<i>Mu</i> 8.00	128.00 ✓
			648.00
		Add 10%	64.80
			712.80
		TOTAL	S\$ 712.80
		ADD GST @ 8%	57.02
		GRAND TOTAL	<u>S\$ 769.82</u>

SINGAPORE DOLLAR SEVEN HUNDRED SIXTY-NINE AND CENTS EIGHTY-TWO ONLY

Parts: \$ 3,018.40  
 SN : 60.00  
 Labour : 1,030.00  
 Supp : 648.00  
 -----  
 \$ 4,756.40  
 XS 700.00  
 -----  
 \$ 4,056.40  
 8% 324.51  
 -----  
 \$ 4,380.91

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company  
Owner ID: 778Z

### Vehicle Details

Vehicle No.: SNG7311D  
Vehicle to be Exported: No  
Intended Deregistration Date: 30 Apr 2023  
Vehicle Make: MERCEDES BENZ  
Vehicle Model: E200 SEDAN AVG (R18 LED)  
Primary Colour: Blue  
Manufacturing Year: 2019  
Engine No.: 26492080001492  
Chassis No.: WDD2130802A672697  
Maximum Power Output: 145.0 kW (194 bhp)  
Open Market Value: \$55,707.00  
Original Registration Date: 24 Oct 2019  
First Registration Date: 24 Oct 2019  
Transfer Count: 0  
Actual ARF Paid: \$72,273.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 23 Oct 2029  
PARF Rebate Amount: \$54,204.00

### Intended COE Rebate Details

COE Expiry Date: 23 Oct 2029  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$48,000.00  
COE Rebate Amount: \$31,096.00  
**Total Rebate Amount: \$85,300.00**

The information contained herein is correct as at 12 Apr 2023

OK