

Huey Yon (LKKAuto)

From: Huey Yon (LKKAuto)
Sent: Friday, 14 April 2023 8:40 AM
To: Operation / Candy Ong
Cc: SUR
Subject: RE: Estimated cost of repair for repairing of vehicle no.: SNG7311D -- Own Damaged Claim

Dear Candy,

As instructed by our client, please proceed to repair the **insured vehicle SNG 7311D on part by part basis. (Excess \$700/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,
Huey Yon | Case Handler
LKK Auto Consultants
phone: 6256-3561 | email: hueyyon@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Operation / Candy Ong <operation@tlauto.com.sg>
Sent: Tuesday, April 11, 2023 1:21 PM
To: 'ClaimsDocManagement' <ClaimsDocManagement@aig.com>
Cc: sharon.lim@allianz.com.sg; janice.koh@allianz.com.sg; SUR <sur@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Estimated cost of repair for repairing of vehicle no.: SNG7311D -- Own Damaged Claim

Dear All,

Please find attached documents for your information and necessary action

The vehicle is now garage at our workshop

Kindly arrange your surveyor to survey the vehicle at an earlier date

Thanks & Regards,

Candy Ong



Tong Luck Auto Pte Ltd

160 Sin Ming Drive

#07-01/06 Sin Ming Autocity

Singapore 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg