



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD
79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT

TEL : FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 28/03/2023

ESTIMATE

NO : QUOT202304-000025(00)
DATE : 14/04/2023
POLICY NO : SP2003907937
VEH REG NO : SMM2032Y
MAKE/MODEL : MERCEDES BENZ S320L (R19 LED)
CHASSIS NO : WDD2221622A464637
ENGINE NO : 27682431002517
REG. DATE : 2019

Estimate Repair Cost to Vehicle No : SMM2032Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Rear door lower chrome - LH	1	148.00	148.00
			148.00
		Add 10%	14.80
			162.80
		TOTAL	S\$ 162.80
		ADD GST @ 8%	13.02
		GRAND TOTAL	S\$ 175.82

SINGAPORE DOLLAR ONE HUNDRED SEVENTY-FIVE AND CENTS EIGHTY-TWO ONLY

Parts : \$ 4,032.60
SN 100.00

Labour 1,840.00

Xs \$ ~~5,972.60~~
1,000.00

8% \$ 4,972.60
397.81

\$ 5,370.41

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE