



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ESTIMATE

NO : QUOT202304-000025(00)

DATE : 11/04/2023

POLICY NO : SP2003907937

VEH REG NO : SMM2032Y

MAKE/MODEL : MERCEDES BENZ S320L (R19
LED)

CHASSIS NO : WDD2221622A464637

ENGINE NO : 27682431002517

REG. DATE : 2019

ATTN : MOTOR CLAIMS DEPT

TEL :

FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 28/03/2023

NOT Notarised
Recovery B&P paint
EX T&A
6 days

Estimate Repair Cost to Vehicle No : SMM2032Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Rear door - LH	1	1,950.00	1,950.00 ✓
2 Rear door weatherstrip - LH	1	238.00	238.00 ✓
3 Rear door trimboard rivets - LH	20	9.00	180.00 ✓
4 Rear door outer handle - LH	1	380.00	380.00 ✓
5 Rear fender - LH	1	3,320.00	3,320.00 ✓
6 Rear fender inner shield - LH	1	228.00	228.00 X
7 Rear bumper	1	1,280.00	1,280.00 X
8 Rear bumper side retainer - LH	1	78.00	78.00 X
9 Rear bumper clips	15	5.50	82.50 X
10 Rear sport rim - LH	1	950.00	950.00 ✓
			8,686.50
		Add 10%	868.65
			9,555.15
SPECIAL NET			
11 Rear tyre - LH	1	480.00	480.00 ?
12 Rear windscreen sealant	1	60.00	60.00 40.00
			540.00
LABOUR			
13 To remove and refit rear windscreen glass	1	180.00	180.00
14 To remove and refit rear cushion seat, speaker board and all inner garnishes and trimboard to facilitates the repair	1	280.00	280.00 120.00
15 To transfer LH rear damaged door interior mechanism and glass to new door	1	150.00	150.00 60.00
16 To remove and refit rear bumper sensor	1	100.00	100.00 X
17 To check and rectify wiring system	1	80.00	80.00 20.00
18 To panel beat and straighten LH rear chassis frame, LH rear fender inner panel, LH rear wheel arch panel, to cut and weld LH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	1,500.00	1,500.00 800.00
19 To putty and spray paint on affected areas	1	1,200.00	1,200.00 60.00
20 To computerise check wheel alignment	1	120.00	120.00
			3,610.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: