

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 14 April 2023 7:56 AM
To: joshua@falconair.com.sg; assignments; SUR
Cc: Meng Yan (LKK Auto)
Subject: RE: SGM 6199U DOA:10/04/2023 (AIS OD)

Dear Joshua,

As instructed by our client , please proceed to repair the **insured vehicle SGM 6199U. Lump Sum Repair. (Excess \$0/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: joshua@falconair.com.sg <joshua@falconair.com.sg>
Sent: Wednesday, April 12, 2023 9:50 AM
To: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Meng Yan (LKK Auto) <mengyan@lkkauto.com>
Subject: desktop survey for SGM6199U DOA:10/04/2023

Dear Sir/Mdm,

Please see attach for SGM6199U damage photos, estimate and SAS.
The front right wheel is turned inwards already.

Thanks and regards,
Joshua Ng
Falcon-Air Auto Services (Tampines)
Tel: 67897997