

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SGM 61994
 at Workshop m/s Falcon A.1 Tynor
 of _____
 Insured: _____
 Policy No. SP2001257650
 Claims No. 202332007083
 Sum Insured: _____ Excess: 0
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$73k.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 30 % 3 Val.: Yes or No
 CA REV / REP. / 24 HRS
 Date: _____ Person Contacted: LIA @ 42501
 Vehicle: 912D IN / OUT

Veh No: SGM 61994 Yr Regn: 26/04/16
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or SA / 1-STFS1
 Make: Audi / AG c.c. 1798
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 126179 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZZ4G8GN080280
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or steer
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil S/Rim / STD A/Rim or
 Tyre Size: F: 225/55R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 10/04/23 D.O.I. 12/4/23
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Aff.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
26/4/23	2sp 17500 cost headly \$4782 L/S \$14,000 inform Justice (red 14,194.50, 50%)

Date/Time, File Pass to? : Preli. Report
 : Final Report

Date/Time, File Return to?

2) 26/4/23-typist

Report Format : Merimen

Lump Sum / L.B.I: (\$ 14,000)

Days Of Repair: 6
 Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: _____
 Transportation: _____
 S + RS, SI _____
 Photos _____
 Others _____
 TOTAL _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	912D
Vehicle Details	
Vehicle No.:	SGM6199U
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Apr 2023
Vehicle Make:	AUDI
Vehicle Model:	A6 1.8 TFSI ULTRA (PI) (NAV)
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	CYG009519
Chassis No.:	WAUZZZ4G8GN080280
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$39,442.00
Original Registration Date:	26 Apr 2016
First Registration Date:	26 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$42,219.00 21109
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Apr 2026
PARF Rebate Amount:	\$27,442.00
Intended COE Rebate Details	
COE Expiry Date:	25 Apr 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,602.00
COE Rebate Amount:	\$15,059.00
Total Rebate Amount:	\$42,501.00

The information contained herein is correct as at 12 Apr 2023

OK

Car Accessories & Products

Pimping up your ride? Browse thousands of car products for even more choices! Read honest reviews by our trusted consumers before you make a purchase.

Post an Advertisement
Sell it yourself! Advertise it at just **\$68 until it's SOLD!**

1 Owner Mint Condition Mazda 6 Executive At \$100k.



High Spec Model With Special Mazda Gloss Paint And Complimentary Agent Svcs Pack Direct Owner StarAd

Lake View Credit Pte Ltd view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Sort by results/page

6 vehicles

[Advanced Search](#)

Search Selection	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
	Audi A6	Audi A6 1.8A TFSI Ultra	\$77,588	\$18,570 /yr	2016	1,798 cc	111,254 km	Luxury	Available
Accident free, well maintained in pristine condition. Clean & neat interior with glossy new paintwork on the exterior. This A6 has gone thr... MV Auto Posted: 12-Apr-2023									
	Audi A6	Audi A6 1.8A TFSI Ultra	\$89,800	\$18,290 /yr	2016	1,798 cc	101,000 km	Luxury	Available
100% accident free, well maintained in pristine condition. Clean and neat interior with original black paint on brown seats. Smooth and s... Posted: 07-Apr-2023									
	Audi A6	Audi A6 1.8A TFSI Ultra	\$77,800	\$19,860 /yr	2016	1,798 cc	-	Luxury	Available
New 6 Month Road Tax! 1 Owner Low Mileage Genuine Unit. No Gimmicks For Price. Perfect Drive Away Condition. No Repair Needed. Fl... Cube Motors Posted: 01-Apr-2023									
	Audi A6	Audi A6 2.0A TFSI	\$91,800	\$20,580 /yr	2016	1,984 cc	70,000 km	Luxury	Available
Pushing Up Till 250bhp, This Unit Has Upgraded RS Steering Wheel And RS Gear Knob With 20 Inch Sport Rims. Vert Mint Condition Wit... Privilege Motors Pte Ltd Posted: 29-Mar-2023									
	Audi A6	Audi A6 1.8A TFSI Ultra S-tronic	\$76,800	\$19,890 /yr	2016	1,798 cc	85,000 km	Luxury	Available
Pristine condition! 1 Owner Only! Full service and all wear and tear parts done up at reputable workshop! 100% loan available from 2.28... This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More Platinum Motoring Posted: 07-Mar-2023									
	Audi A6	Audi A6 3.0A TFSI Quattro S-tronic	\$135,800	\$24,480 /yr	2016	2,995 cc	-	Luxury	Available
\$0 Downpayment & Drive Away Available. Will provide 1 year Engine & Gearbox Warranty. Buy in a peace of mind without any issue as a... Posted: 27-Feb-2023									

Save this search criteria, to get email alerts whenever a match is found.

Make: Model: Price: Depreciation: Reg Date: Eng Cap: Mileage: Veh Type: Status:

For old advertisements, view Expired ads

results/page

[Compare](#)



FALCON-AIR

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001257650	Date of Loss:	10/04/2023
Vehicle Reg. No.:	SGM6199U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	XU BINGTAO		

Make/Model:	AUDI A6, 1.8 TFSI S-TRONIC (A)	Vehicle Reg. Date:	26/04/2016
Vehicle Colour:	BLACK		
Engine No:	CYG009519	Chassis No:	WAUZZZ4G8GN080280
Odometer:	80000 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 10

*not allowed
see
Euros & N.L
12/4/23
2/5 = 14,000
6 days*

Present Location: FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)

COST OF CLAIMS

	Amount
Parts	23,797.50
Miscellaneous Items	0.00
Labour	4,100.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	27,897.50
+ GST 8.00% (S\$)	2,231.80
Nett Amount (S\$)	30,129.30

This claim is handled by: JOSHUA NG

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Apr 2023)
Parts: 143 AUDI A6 1.8 TFSI S-tronic (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Falcon-Air Auto Services Pte Ltd/SGM6199U/11/04/2023 09:34
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*O/S HEADLAMP <i>holder crs</i>	0.00	0.00	*3,500.00 F ✓
2	1		*O/S HEADLAMP LOWER BRACKET <i>crs</i>	0.00	0.00	*150.00 F ✓
3	1		*O/S HEADLAMP PANEL <i>3rd</i>	0.00	0.00	*240.00 F ✓
4	1		*FRONT SUPPORT PANEL <i>2</i>	0.00	0.00	*780.00 F ✓
5	1		*O/S FRONT FENDER <i>3rd</i>	0.00	0.00	*840.00 F ✓
6	1		*O/S FRONT FENDER INNER SHIELD <i>100</i>	0.00	0.00	*260.00 F ✓
7	1		*O/S FRONT FENDER INNER SHIELD CLIPS <i>ner</i>	<i>s/n</i> 0	0.00	*40.00 FS ✓
8	1		*O/S FRONT FENDER INNER SHIELD RIVETS <i>NS</i>	0	0.00	*60.00 FS ✓
9	1		*O/S FRONT FENDER STONE GUARD STICKER <i>ner</i>	<i>s/n</i> 0	0.00	100 *150.00 FS ✓
10	1	<i>fuel</i>	*O/S REAR DOOR STONE GUARD STICKER <i>ner</i>	<i>s/n</i> 0	0.00	100 *150.00 FS ✓
11	1		*RADIATOR GRILLE <i>crs</i>	740	0.00	0.00 *1,100.00 F ✓
12	1		*FRONT BUMPER <i>2/torn</i>	1420	0.00	0.00 *1,610.00 F ✓
13	1		*O/S FRONT BUMPER SIDE RETAINER <i>crs</i>	0.00	0.00	*155.00 F ✓
14	1		*FRONT BUMPER CLIPS <i>ner</i>	<i>s/n</i> 0	0.00	*40.00 FS ✓
15	1		*FRONT BUMPER RIVETS <i>ner</i>	<i>s/n</i> 0	0.00	*60.00 FS ✓
16	1		*O/S FRONT BUMPER AIR GRILLE <i>ms</i>	0.00	0.00	*245.00 F ✓
17	1		*O/S FRONT BUMPER AIR GRILLE CHROME <i>ms</i>	0.00	0.00	*165.00 F ✓
18	1		*O/S FRONT BUMPER SENSOR <i>11</i>	0.00	0.00	*240.00 F X
19	4		*FRONT BUMPER SENSOR ORING <i>11</i>	0.00	0.00	*60.00 F X
20	4		*FRONT BUMPER SENSOR BRACKET <i>11</i>	0.00	0.00	*220.00 F X
21	1		*FRONT BUMPER TOP COVER <i>100</i>	0.00	0.00	*195.00 F ✓
22	1		*O/S FRONT AIR GUIDE <i>11</i>	0.00	0.00	*160.00 F X
23	1		*O/S FRONT TYRE <i>SVC</i>	0.00	0.00	*400.00 F X
24	1		*O/S FRONT RIM <i>Went 800 s/n</i>	<i>s/n</i> 0.00	0.00	*1,050.00 F ✓
25	1		*O/S FRONT SHOCK ABSORBER <i>3rd</i>	0.00	0.00	*450.00 F ✓
26	1		*O/S FRONT SHOCK LOWER ARM <i>ner</i>	0.00	0.00	*610.00 F ✓
27	1		*O/S FRONT SHOCK CONTROL ARM <i>3rd</i>	0.00	0.00	*610.00 F ✓
28	1		*O/S FRONT WHEEL HUB <i>2nd</i>	0.00	0.00	*420.00 F ✓
29	2		*O/S FRONT UPPER ARM <i>3rd</i>	0.00	0.00	*820.00 F ✓
30	1		*O/S FRONT LINKAGE <i>11</i>	0.00	0.00	*95.00 F X
31	1		*FRONT ANTI ROLL BAR <i>11</i>	0.00	0.00	*650.00 F X
32	1		*O/S FRONT DRIVESHAFT <i>3rd/100</i>	0.00	0.00	*1,800.00 F ✓
33	1		*STEERING RACK AND PINION <i>3rd/100</i>	0.00	0.00	*2,500.00 F ✓
34	1		*O/S SIDE SKIRT <i>R</i>	0.00	0.00	*1,800.00 F X
35	1		*O/S SIDE SKIRT CLIPS <i>11</i>	0	0.00	*60.00 FS X

F=Franchise part. S=SpcNett.

Sub Total (S\$)	21,685.00
+ Margin on L,N Items 10.00% (S\$)	2,112.50
Total Parts (S\$)	23,797.50

Falcon-Air Auto Services Pte Ltd/SGM6199U/11/04/2023 09:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO FOCUS HEADLAMP	New	20 50.00
2	TO CODE AND PROGRAM HEADLAMP MODULE	New	100 280.00
3	TO REPLACE FRONT UNDERCARRIAGE	New	300 380.00
4	TO FIT TYRE ON NEW RIM PLUS BALANCING	New	11X 50.00
5	TO CONDUCT 4 WHEEL COMPUTERISE WHEEL ALIGNMENT	New	100 120.00
6	TO DIAGANOSE AND RESET CHECK LIGHTS	New	111X 300.00
7	TO REMOVE/REFIX AIR CON CONDENSER, PIPE ETC TO VACUUM AND TOP UP AIR CON GAS	New	111X 120.00
8	TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, CUT/REWELD FRONT SUPPORT PANEL, REPLACEMENT OF PARTS AND ALIGN THE SAME	New	600 1,000.00
9	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	New	1100 1,800.00
Gross Labour Cost (S\$)			4,100.00

Falcon-Air Auto Services Pte Ltd/SGM6199U/11/04/2023 09:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 15120
+ 10%
P-16632
S.N-1140
2-2220
Supp-297
20289
302
14202.30

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 18 Apr 2023)

Parts: 143 **AUDI A6 1.8 TFSI S-tronic (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SGM6199U/18/04/2023 11:54

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*O/S FRONT FENDER INNER BRACKET Dis	0.00	0.00	*105.00 F ✓
2	1		*O/S FRONT FENDER INNER SHIELD (FRONT) 7011	0.00	0.00	*165.00 F ✓
Sub Total (S\$)						270.00
+ Margin on L,N Items 10.00% (S\$)						27.00
Total Parts (S\$)						297.00

F=Franchise part.

Falcon-Air Auto Services Pte Ltd/SGM6199U/18/04/2023 11:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS