



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23003769/Kvy3e2 Date: 27/04/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SNK 1847T	Veh. Inspected	SGT 3729Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	BVS23/0268	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	12/04/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MAZDA 3 (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	JM6BM42A8G0326549	Colour	METALLIC DARK BLUE
	Odometer	60837 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	BRIDGESTONE	3 mm
	L/H Front Tyre	205/60 R16	BRIDGESTONE	3 mm
	R/H Rear Tyre	205/60 R16	BRIDGESTONE	7 mm
	L/H Rear Tyre	205/60 R16	BRIDGESTONE	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	04/04/2023	Inspection Date	17/04/2023
	Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.		
<b>5a. Remarks</b>				
	A)REGISTRATION DATE: 26 FEB 2016 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	