

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

*Not Withain
 11 Day @ 3550/h
 Preparing After Paint
 6 days*

Estimate : TP23/012

Date : 11/04/2023
 Vehicle Num. : SGT 3729Z
 Make/Model : MAZDA 3-2016
 Chassis/Eng# : JM6BM42A8G0326549/P520334809
 Accident Date : 04/04/2023
 Claim No. : BVS23/0268-PRS-PY
 Reference : LYB/SGT3729Z/Liberty/sl
 Policy No. :

LIBERTY INSURANCE PTE LTD
 51 CLUB STREET #03-00
 CITYSTATE HOUSE SINGAPORE 069428

Attention : Motor Claim Department
 Contact : 62218611 Fax No. : 62241047

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

REAR BUMPER BRACKET/RH
 REAR W/SCREEN SEALANT
 REAR W/SCREEN INNER SEAL

List TotalS\$:

D/I 38.00
na 40.00
na 40.00 *30.00*

 118.00

NETT ITEMS :

REAR EMBLEM 'MAZDA 3'
 REAR EMBLEM 'SKY ACTIVE'
 REAR EMBLEM LOGO
 REAR TAILLAMP/RH
 REAR REFLECTOR/RH
 REAR BUMPER TOWING COVER
 REAR BUMPER RETAINER/RH
 REAR FENDER INNER SHIELD/RH
 REAR FENDER/RH

Nett Total S\$:

10.00% Discount S\$:

na 56.20 X
na 66.80 X
na 78.20 X
cm 866.80
na 498.50 X
na 29.10
cm 48.00
D/I 268.90
na 988.80

2,901.30
 290.13

 2,611.17

SPECIAL NETT ITEMS :

REAR BUMPER FASTENER

5.00 *na* 25.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

LIBERTY INSURANCE PTE LTD
 51 CLUB STREET #03-00
 CITYSTATE HOUSE SINGAPORE 069428

Attention : Motor Claim Department
 Contact : 62218611 Fax No. : 62241047

Estimate : TP23/012

Date : 11/04/2023
 Vehicle Num. : SGT 3729Z
 Make/Model : MAZDA 3-2016
 Chassis/Eng# : JM6BM42A8G0326549/P520334809
 Accident Date : 04/04/2023
 Claim No. : BVS23/0268-PRS-PY
 Reference : LYB/SGT3729Z/Liberty/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	5	REAR BUMPER EXTENSION FASTENER	5.00	25.00 <i>nn</i> X
3.	5	REAR BUMPER EXTENSION GROMMET SCREW	5.00	25.00 <i>nn</i> X
4.	5	RIVERT	8.00	40.00 <i>nn</i> X
5.	5	REAR FENDER INNER SHIELD CLIPS	5.00	25.00 <i>nn</i> ✓
Special Nett Total S\$:				140.00
LABOUR :				150.00 <i>120</i>
TO REMOVE/REFIT REAR W/SCREEN TO FACILITATE REPAIRS				180.00 <i>100</i>
TO REMOVE/ REFIX REAR INTERIOR FIXING, GARNISH, TRIMS				120.00 <i>30</i>
TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS				60.00 <i>10</i>
TO CHECK WATER SEEPAGE				60.00 <i>20</i>
TO CHECK WORKING FUNCTION				120.00 <i>50</i>
LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTION				<i>nn</i> 120.00 X
TO CHECK COMPUTERISE ALIGNMENT				<i>nn</i> 180.00 X
TO REPAIR & RESPRAY AFFECTED RIGHT REAR RIM				
TO REPAIR, PANEL BEAT ON AFFECTED RIGHT REAR PANEL, CUT & WELD ON REPLACED PANEL & LABOUR TO REPLACE THE ABOVE				

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
Tel No. : 64534177 Fax No. : 64593724
E-Mail : limyewboo@singnet.com.sg
Website : www.limyewboo.com.sg
Buss. Reg. No. : 20051400L

LIBERTY INSURANCE PTE LTD
51 CLUB STREET #03-00
CITYSTATE HOUSE SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Estimate : TP23/012

Date : 11/04/2023
Vehicle Num. : SGT 3729Z
Make/Model : MAZDA 3-2016
Chassis/Eng# : JM6BM42A8G0326549/P520334809
Accident Date : 04/04/2023
Claim No. : BVS23/0268-PRS-PY
Reference : LYB/SGT3729Z/Liberty/sl
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		PARTS		1,500.00 <i>7001</i>
		TO PUTTY, PRIMER & SPRAY PAINT ON RIGHT REAR DOOR, REAR FENDER, REAR BUMPER & AFFECTED REAR BOOT LID & REAR REVERSE SENSOR & AFFECTED DOOR HANDLE USING 2K PAINT		1,500.00 <i>6601</i>
		Labour Total S\$:		3,990.00

7801.74

E. & O.E.

Total S\$: 6,859.17



for LIM YEW BOO SPRAY PAINT CO.