Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

> 79 Robinson Road #09-01 Singapore 068897

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: JANICE KOH Date: 26 Apr 2023

Preliminary Advice

Vehicle No : EW122B **Accident Date** : 07/04/2023 Policy No. : SP2003090998 Make : HYUNDAI AVANTE Assignment Date : 11/04/2023 Excess : S\$600.00

Date of Inspection : 26/04/2023 Est. Duration of Repair : 3

: KAN FOOK SING MOTOR WORKSHOP (DEFU) Inspection At

BLK 8 DEFU SOUTH STREET 1, DEFU INDUSTRIAL CITY #04-29

SINGAPORE 533758

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,131.90
Revised Amount	:S\$	2,493.50
Check Items (Estimated)	:S\$	48,40
Total	:S\$	2,541.90

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 110,000.00 COE / PARF Rebate :S\$ 37,924.00

Salvage Value :S\$

Margin for Repair :S\$ 72,076.00

Remarks

(x)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kir	ndly
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments :the vehicle repair on part by parts basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.