

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2023)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHD6699D/11/04/2023 15:04	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR TRUNK LID LOGO (HYBRID)	25.00	0.00	*52.40 FL ✓
2	1		*REAR TRUNK LID LOGO (PRIUS)	25.00	0.00	*52.90 FL ✓
3	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	25.00	0.00	*60.80 FL ✓
4	1		*REAR TRUNK LID GARNISH OUTSIDE	25.00	0.00	*1,054.71 FL ✓
5	1		*TAIL LAMP LOWER LH	25.00	0.00	*570.00 FL ✓
6	1		*TAIL LAMP SIDE LH	25.00	0.00	*256.00 FL ✓
7	1		*REAR BUMPER	25.00	0.00	*551.89 FL ✓
8	1		*REAR BUMPER CENTRE MOULDING	25.00	0.00	*654.96 FL ✓
9	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	*378.32 FL ✓
10	10		*REAR BUMPER CLIPS	25.00	0.00	*22.00 FL ✓
11	2		*REAR BUMPER REFLECTOR LH/RH	25.00	0.00	*110.00 FL ✓
12	1		*REAR BUMPER TOW COVER RH	25.00	0.00	*82.70 FL ✓
13	2		*REAR BUMPER SIDE RETAINER LH/RH	25.00	0.00	*225.40 FL ✓
14	1		*REAR REVERSE SENSOR	25.00	0.00	*135.70 FL ✓
15	1		*REAR BUMPER MAT	0	0.00	*50.00 FS ✓
16	1		*REAR NUMBER PLATE W/HOLDER	25.00	0.00	*55.00 FL ✓
17	1		*BOOTLID COMFORT /TEL NUMBER STICKER	25.00	0.00	*60.00 FL ✓
18	1		*BOOTLID COMFORT APP STICKER	25.00	0.00	*40.00 FL ✓

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	4,412.78
- List Item Discount on L Items (S\$)	1,090.70
Total Parts (S\$)	3,322.08

ComfortDelGro Engineering Pte Ltd/SHD6699D/11/04/2023 15:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	350	900.00
2	SPRAY PAINTING	New	500	800.00
3	CHECK WIRING/ LIGHTING	New	30	60.00
4	REMOVE/REFIX REVERSE SENSOR	New	30	60.00
5	TUFF KOTE	New	MAX	90.00
6	TOWING FEE	New	towing ? receipt	60.00

Gross Labour Cost (\$\$) 1,970.00

ComfortDelGro Engineering Pte Ltd/SHD6699D/11/04/2023 15:04. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tan Jiah 97495744
 WP 12/4/23 @ 430pm
 Tan Jiah C / Merimen.com
 2-3 days
 P/V Repair before paint

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before start of painting
- To display demand parties during a survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental charges must be resurveyed and subject to approval from Insurance Company

Acknowledged as Repairer

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Apr 2023)
Parts: 144 TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHD6699D/18/04/2023 13:36
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR TRUNK LID	25.00	0.00	BT✓ *1,303.29 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)						1,303.29
- List Item Discount on L Items (S\$)						325.82
Total Parts (S\$)						977.47

ComfortDelGro Engineering Pte Ltd/SHD6699D/18/04/2023 13:36. Not valid without Reference section.
Generated using Merimen e-Claims IEAS