



## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

HKK

**TP INSURER:** **Tokio Marine Insurance Singapore Ltd (HQ)**  
**CTPL**

Singapore

**PARTICULARS OF CLAIM**

|                               |                                            |                    |                   |
|-------------------------------|--------------------------------------------|--------------------|-------------------|
| Claim Type:                   | THIRD PARTY                                | Ref. No:           |                   |
| Policy No:                    |                                            | Date of Loss:      | 10/04/2023        |
| Vehicle Reg. No.:             | <b>SHD6699D</b>                            | Driveable?         | NO                |
| Party At Fault:               | UNKNOWN                                    |                    |                   |
| Make/Model:                   | TOYOTA PRIUS TAXI, 1.8 (A)                 | Vehicle Reg. Date: | 30/06/2020        |
| Vehicle Colour:               | BLUE                                       | Gen Condition:     | GOOD              |
| Engine No:                    | 2ZR2G82079                                 | Chassis No:        | JTDKB3FU303091567 |
| Odometer:                     | 174054 KM                                  |                    |                   |
| Paint Type:                   |                                            |                    |                   |
| List Item Discount:           | 25.00 %                                    |                    |                   |
| Total Loss?                   | <b>NO</b>                                  |                    |                   |
| Est. Duration of Repair (day) | 5                                          |                    |                   |
| Present Location:             | COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) |                    |                   |

**COST OF CLAIMS**

|                          | <b>Amount</b>   |
|--------------------------|-----------------|
| Parts                    | 3,322.08        |
| Miscellaneous Items      | 11.00           |
| Labour                   | 1,970.00        |
| Paintwork Labour         | 0.00            |
| Towing                   | 0.00            |
| <b>Gross Total (S\$)</b> | <b>5,303.08</b> |
| <b>+ GST 8.00% (S\$)</b> | <b>424.25</b>   |
| <b>Nett Amount (S\$)</b> | <b>5,727.33</b> |

**This claim is handled by: CHIANG LIAT CHOON**

Generated using Merimen e-Claims Internet Estimation & Adjusting System



**REPAIR DETAILS****Reference**

|                                                                                |                                                                                                                                                                              |
|--------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Part Source:</b> MRM-SG                                                     | Version: 1.0 (Last Synchronised: 11 Apr 2023)                                                                                                                                |
| <b>Parts:</b> 144                                                              | TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)                                                                                                                  |
| <b>Labour:</b> Repairer's                                                      | (Price-denominated Standard List)                                                                                                                                            |
| <b>Print Code:</b> ComfortDelGro Engineering Pte Ltd/SHD6699D/11/04/2023 15:04 |                                                                                                                                                                              |
| <b>Validity:</b>                                                               | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>                                                           | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |

**Estimates on Parts**

| No. | Qty | Part No. | Particulars                          | %Disc | %Depr           | Amount       |
|-----|-----|----------|--------------------------------------|-------|-----------------|--------------|
| 1   | 1   |          | *REAR TRUNK LID LOGO (HYBRID)        | 25.00 | 0.00 <i>new</i> | *52.40 FL    |
| 2   | 1   |          | *REAR TRUNK LID LOGO (PRIUS)         | 25.00 | 0.00 <i>new</i> | *52.90 FL    |
| 3   | 1   |          | *REAR TRUNK LID LOGO (TOYOTA STAR)   | 25.00 | 0.00 <i>X</i>   | *60.80 FL    |
| 4   | 1   |          | *REAR TRUNK LID GARNISH OUTSIDE      | 25.00 | 0.00 <i>new</i> | *1,054.71 FL |
| 5   | 1   |          | *TAIL LAMP LOWER LH                  | 25.00 | 0.00 <i>?</i>   | *570.00 FL   |
| 6   | 1   |          | *TAIL LAMP SIDE LH                   | 25.00 | 0.00 <i>?</i>   | *256.00 FL   |
| 7   | 1   |          | *REAR BUMPER                         | 25.00 | 0.00 <i>de</i>  | *551.89 FL   |
| 8   | 1   |          | *REAR BUMPER CENTRE MOULDING         | 25.00 | 0.00 <i>de</i>  | *654.96 FL   |
| 9   | 1   |          | *REAR BUMPER REINFORCEMENT           | 25.00 | 0.00 <i>?</i>   | *378.32 FL   |
| 10  | 10  |          | *REAR BUMPER CLIPS                   | 25.00 | 0.00 <i>new</i> | *22.00 FL    |
| 11  | 2   |          | *REAR BUMPER REFLECTOR LH/RH         | 25.00 | 0.00 <i>X</i>   | *110.00 FL   |
| 12  | 1   |          | *REAR BUMPER TOW COVER RH            | 25.00 | 0.00 <i>de</i>  | *82.70 FL    |
| 13  | 2   |          | *REAR BUMPER SIDE RETAINER LH/RH     | 25.00 | 0.00 <i>?</i>   | *225.40 FL   |
| 14  | 1   |          | *REAR REVERSE SENSOR                 | 25.00 | 0.00 <i>new</i> | *135.70 FL   |
| 15  | 1   |          | *REAR BUMPER MAT                     | 0     | 0.00 <i>new</i> | *50.00 FS    |
| 16  | 1   |          | *REAR NUMBER PLATE W/HOLDER          | 25.00 | 0.00 <i>bt</i>  | *55.00 FL    |
| 17  | 1   |          | *BOOTLID COMFORT /TEL NUMBER STICKER | 25.00 | 0.00 <i>new</i> | *60.00 FL    |
| 18  | 1   |          | *BOOTLID COMFORT APP STICKER         | 25.00 | 0.00 <i>new</i> | *40.00 FL    |

F=Franchise part, S=SpcNett, L=ListItemDisc.

|                                              |                 |
|----------------------------------------------|-----------------|
| <b>Sub Total (S\$)</b>                       | <b>4,412.78</b> |
| <b>- List Item Discount on L Items (S\$)</b> | <b>1,090.70</b> |
| <b>Total Parts (S\$)</b>                     | <b>3,322.08</b> |

ComfortDelGro Engineering Pte Ltd/SHD6699D/11/04/2023 15:04. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

| No                         | Qty | Particulars          | Amount       |
|----------------------------|-----|----------------------|--------------|
| <b>Miscellaneous Items</b> |     |                      |              |
| 1                          | 1   | OD/TP Case (Insurer) | 11.00        |
| <b>Sub Total (\$\$)</b>    |     |                      | <b>11.00</b> |

## Estimates on Labour

| No                              | Particulars                 | Lab.Type           | Amount          |
|---------------------------------|-----------------------------|--------------------|-----------------|
| <b>Labour Items</b>             |                             |                    |                 |
| 1                               | PANEL BEATING               | New 350            | 900.00          |
| 2                               | SPRAY PAINTING              | New 500            | 800.00          |
| 3                               | CHECK WIRING/ LIGHTING      | New 30             | 60.00           |
| 4                               | REMOVE/REFIX REVERSE SENSOR | New 30             | 60.00           |
| 5                               | TUFF KOTE                   | New X              | 90.00           |
| 6                               | TOWING FEE                  | New towing receipt | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                             |                    | <b>1,970.00</b> |

ComfortDelGro Engineering Pte Ltd/SHD6699D/11/04/2023 15:04. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanji 97495744  
wp' 12/4/23 @ 430pm  
Tanji C/WhatsApp  
2-3 days  
P/R. Repair before paint

**LKK Auto Consultants** hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental work(s) must be resurveyed and subject to final approval from Insurance Company

Authorised by Repairer  
Signature:

### Workshops

205 Braddell Road Singapore 579701  
59 Loyang Drive Singapore 508969  
383 Sin Ming Drive Singapore 575717  
45 Pandan Road Singapore 609286

Date/Time: 11.04.2023 13:41

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5892651

JC NO305550946


|                                                            |                                |  |                       |                                  |                 |
|------------------------------------------------------------|--------------------------------|--|-----------------------|----------------------------------|-----------------|
| CUSTOMER<br><br>MS<br>CUSTOMER NO<br>ADDRESS<br>(R)<br>(P) | COMFORT TRANSPORTATION PTE LTD |  | REGN NO:              | SHD6699D                         | MILEAGE         |
|                                                            | 7010045                        |  | MAKE:                 | TOYOTA                           | FUEL            |
|                                                            | 383 SIN MING DRIVE             |  | MODEL                 | PRIUS HYBRID(G4A10.04.2023 20:35 | E.....1/2.....F |
|                                                            | Singapore SINGAPORE 575717     |  | YR OF MANU            | 30.09.2020                       | DATE/TIME IN    |
|                                                            | 65508755                       |  | CHASSIS CODE          | JTDKB3FU303091567                | TARGET DATE     |
| COUNT CARD NO.                                             |                                |  | COMPLETION DATE/TIME: |                                  |                 |

Accident Date: 10.04.2023

ATURE: 3P 10.04.2023

### JOB DESCRIPTION

Sl/NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

No.: SHD6699D

CHIANG

Vehicle No.:

SHD6699D

of Service Advisor

Signature/Date

Name of Service Advisor

Date

eturned to Service Reception upon collection

To be kept by Security Guard