

TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01

SINGAPORE 068897

ATTN: MOTOR CLAIMS DEPT

TEL :

FAX:

YOUR REF NO

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 02/04/2023

ESTIMATE

NO : QUOT202304-000028(00)

DATE : 12/04/2023 POLICY NO : SP2003902365

VEH REG NO : GBL5879L

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI PANEL VAN LONG AT ABS 5DR

CHASSIS NO : W1V44760323891533

ENGINE NO : 65195035425360

REG. DATE : 2021

Estimate Repair Cost to Vehicle No: GBL5879L

	Description	Quantity	Unit Price	Amount
			<u>\$\$</u>	<u>S\$</u>
	PARTS	4	050.00	050.00
1	Bonnet	1	950.00	950.00
2	Bonnet hinges - RH / LH	2	85.00	170.00
3	Bonnet lock	1	115.00	115.00
4	Bonnet catch	1	45.00	45.00
5	Bonnet pull handle	1	98.00	98.00
6	Bonnet cable	1	48.00	48.00
7	Support panel	1	325.00	325.00
8	Support panel top garnish	. 1	78.00	78.00
9	Support panel top bracket - RH / LH	1	23.00	23.00
10	Brace panel	1	88.00	88.00
11	Headlamp assy - LH	1	580.00	580.00
12	Front bumper	1	780.00	780.00
13	Front bumper reinforcement	1	620.00	620.00
14	Front bumper side retainer - LH	1	58.00	58.0
15	Front bumper inner carrier - LH	1	115.00	115.00
16	Front bumper centre logo	1	92.00	92.0
17	Front bumper support - LH	1	58.00	58.0
18	Support panel side sponge - LH	1	24.00	24.0
19	Front bumper holder - LH	1	24.00	24.0
20	Front bumper lower frame	1	226.00	226.0
21	Front bumper under cover	1	112.00	112.00
22	Front grille inner support	1	480.00	480.0
23	Front fender - LH	1	590.00	590.0
24	Front fender wheel house extension member- LH	1	780.00	780.0
25	Front fender inner shield - LH	1	125.00	125.0
26	Front fender inner shield cover - LH	1	30.00	30.0
27	Front fender rail - LH	1	12.00	12.0
28	Front fender - LH	1	1,050.00	1,050.0
	Front door hinges - LH	2	112.00	224.0
			Add 10%	7,970.0 742.0
				8,712.0
20	SPECIAL NET	4	25.00	25.0
30	Front door "company" sticker	1	25.00	∠5.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

FAX:

79, ROBINSON ROAD #09-01

SINGAPORE 068897

NO

: QUOT202304-000028(00)

DATE

: 12/04/2023

POLICY NO

ESTIMATE

: SP2003902365

VEH REG NO : GBL5879L

MAKE/MODEL: MERCEDES BENZ VITO 114 CDI PANEL VAN LONG AT ABS 5DR

CHASSIS NO : W1V44760323891533

ENGINE NO : 65195035425360

ACCIDENT DATE : 02/04/2023

CLAIM TYPE : OWN DAMAGE

ATTN: MOTOR CLAIMS DEPT

TEL:

YOUR REF NO

REG. DATE : 2021

Estimate Repair Cost to Vehicle No: GBL5879L

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
Front quater glass sealant - LH	1	40.00	40.00
			65.00
LABOUR			
To remove and refit LH quater glass to facilitates the repairs	1	80.00	80.00
To transfer LH front door interior mechanism and glass to new door	1	150.00	150.00
To check and rectify wiring system	1	80.00	80.00
To panel beat and straighten LH front fender inner panel, LH front chassis frame, LH front door pillar, to cut and weld LH front wheel house extension member, including replacement of parts and align where necesary, to refit and adjust the same	1	1,800.00	1,800.00
To putty and spray paint on affected areas	1	1,500.00	1,500.00
To compterise check wheel alignment	1	120.00	120.00
		_	3,730.00
		TOTAL	S\$ 12,507.00
	A	DD GST @ 8%	1,000.56
		GRAND TOTAL	
	Front quater glass sealant - LH LABOUR To remove and refit LH quater glass to facilitates the repairs To transfer LH front door interior mechanism and glass to new door To check and rectify wiring system To panel beat and straighten LH front fender inner panel, LH front chassis frame, LH front door pillar, to cut and weld LH front wheel house extension member, including replacement of parts and align where necesary, to refit and adjust the same To putty and spray paint on affected areas	Front quater glass sealant - LH LABOUR To remove and refit LH quater glass to facilitates the repairs 1 To transfer LH front door interior mechanism and glass to new door To check and rectify wiring system 1 To panel beat and straighten LH front fender inner panel, LH front chassis frame, LH front door pillar, to cut and weld LH front wheel house extension member, including replacement of parts and align where necesary, to refit and adjust the same To putty and spray paint on affected areas 1 To compterise check wheel alignment A	Front quater glass sealant - LH 1 40.00 LABOUR To remove and refit LH quater glass to facilitates the repairs 1 80.00 To transfer LH front door interior mechanism and glass to new 1 150.00 door To check and rectify wiring system 1 80.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To panel beat and straighten LH front fender inner panel, LH front 1 1,800.00 To comptensive fender in fender inner panel, LH front 1 1,800.00 To comptensive fender in fender inner panel, LH front 1 1,800.00 To comptensive fender in fender inner panel, LH front 1 1,800.00 To comptensive fender in fender inner panel, LH front 1 1,800.00 To comptensive fender in fender inner panel, LH front 1 1,800.00 To comptensive fender in fender inner panel, LH front 1 1,800.00 To comptensive fender in fender inner panel, LH front 1 1,800.00 To comptensive fender in fender inner panel, LH front 1 1,800.00 To comptensive fender in fender inner panel, LH front 1 1,800.00 To comptensive fender in fender inner panel, LH front 1 1,800.00 To comptensive fender in fender inner

SINGAPORE DOLLAR THIRTEEN THOUSAND FIVE HUNDRED SEVEN AND CENTS FIFTY-SIX ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SJ0G2343001U / JP Knights Pte Ltd ENTRY DATE & TIME: 03/04/2023 15:58 (SGT) SUBMITTED BY: Siti VERSION: 1 (03/04/2023 15:58 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 A The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for Investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the Jodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

03/04/2023 15:58 (SGT) **Actual Driver** 02/04/2023 09:00 (SGT) Woodlands Street 31, Singapore NEXT TO BLK 343 OSCP Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number **GBL5879L**

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE

LTD

Employment

Commercial vehicle

Yes

Company Reg No 1XXXXX778Z

Email Address too tong.tan@mercedes-benz.com

Mobile Phone No (Phone) +65-88511742 Alternative Phone No (Office) +65-82821711

VEHICLE PARTICULARS

Manufacturer Mercedes Model Vito Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

Auto

CC 2143

INSURANCE COMPANY

Name of Insurance Company Allianz Insurance Singapore Pte. Ltd. Policy Number / Cover Note Number SP2003902365

DRIVER

Name of Driver MOHAMMAD NOH BIN OSMAN NRIC No SXXXX586Z Date Of Birth 30/08/1974

Occupation Outdoor Date Of Driving Pass 28/11/2016

Driving experience 6 YEARS AND 5 MONTHS

Gender Male

Mobile Number (Phone) +65-88511742

Alt, Phone Number

Email Addresstoo_tong.tan@mercedes-benz.comAddress38 BEDOK SOUTH ROAD #04-653

Address complement

Postcode 460038
Is the driver the policyholder? No
If No, Relationship of the Driver with the Insured Hirer
Does Driver Own Other Vehicles? No

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collided into Parked Vehicle

Weather Conditions Clear Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Yes
Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

No
Translator's name

Translator's ID Translator's phone number Translator's email -

Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

ON O2/04/2023 AROUND 0900HRS I VEHICLE A BEARING REGISTRATION NUMBER (GBL5879L) WAS DRIVING AT WOODLAND STREET 31 NEXT TO BLOCK 343 OSCP, AS I WAS LOOKING FOR A PARKING SLOT TO PARK VEHICLE (A) ACCIDENTALLY OVER STEER AND COLLIDED TO PARKED VEHICLE BEARING REGISTRATION NUMBER (YP6331A) AND THE FORCE OF IMPACT MADE VEHICLE (B) MOVED AND HIT ANOTHER VEHICLE C BEARING REGISTRATION NUMBER (SNB4862B) WHICH WAS NEXT TO VEHICLE (B).

I COULDN'T GET THE VEHICLE (B) CONTACT DETAILS AS THE DRIVER WAS NOT AROUND, BUT I DO ABLE TO EXCHANGE PARTICULARS WITH THE VEHICLE (C) DRIVER, NO INJURIES HAPPEND DURING THE ACCIDENT.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YP6331A



Vehicle Manufacturer Isuzu Vehicle Model Vehicle Variant Vehicle Colour

Commercial vehicle

Vehicle Category Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver) 0

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SNB4862B Vehicle Manufacturer Honda Vehicle Model Vehicle Variant Vehicle Colour Blue Vehicle Category Private car

Name of Driver MOI WENG KEONG, EDWIN

NRIC No SXXXX964B

Contact Number (Phone) +65-84392939

Address

Address complement Postcode Insurance Company Name

Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please correctly report the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any willful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims.
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (v) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(Collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents(including their lawyers/law firms), which may be steet outside of Singapore, for one or more of the above Purposes.

FLASH ACCIDENT COME PROPERTING OFFICER FRO VICKY

Witnessed by Reporting Centre


Policyholder's Signature / Date &

Time

Driver's Signature (if driver is not the policyholder) / Date & Time 02042023 — 1430

Personnel

Sketch Plan



Describe Circumstances of the Accident

ON 02/04/2023 AROUND 0900HRS I VEHICLE A BEARING REGISTRATION NUMBER (GBL5879L) WAS DRIVING AT WOODLAND STREET 31 NEXT TO BLOCK 343 OSCP, AS I WAS LOOKING FOR A PARKING SLOT TO PARK VEHICLE (A) ACCIDENTALLY OVER STEER AND COLLIDED TO PARKED VEHICLE BEARING REGISTRATION NUMBER (YP6431A) AND THE FORCE OF IMPACT MADE VEHICLE (B) MOVED AND HIT ANOTHER VEHICLE C BEARING REGISTRATION NUMBER (SNB4862B) WHICH WAS NEXT TO VEHICLE (B) I COULDN'T GET THE VEHICLE (B) CONTACT DETAILS AS THE DRIVER WAS NOT AROUND, BUT I DO ABLE TO EXCHANGE PARTICULARS WITH THE VEHICLE (C) DRIVER, NO INJURIES HAPPEND DURING THE ACCIDENT.

Declaration

I/We declare the foregoing particulars are true in every respect.



FLASH ACCIDENT COIDER REPORTING OFFICER FRO VICKY

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 02042023 —— 1430 Witnessed by Reporting Centre Personnel









Allianz Insurance Singapore Pte. Ltd.

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP.189 OF THE REVISED EDITION) (REPUBLIC OF SINGAPORE)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1996 (REPUBLIC OF SINGAPORE)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES,1960

OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Certificate Number SP2003902365

Date of Issue 27 December 2022

COMPREHENSIVE - AUTHORISED WORKSHOP Coverage

Policyholder MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE. LTD.

Finance Company

Period of Insurance 01 January 2023 To 31 December 2023 (both dates inclusive)

Registration Number GBI 58791

Chassis Number of Vehicle W1V44760323891533

Persons or Classes of Persons Entitled to Drive*:

- (a) The Policyholder.
- (b) Any other person who is driving on the Policyholder's order or with his/her permission or to whom the
- * Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment or regulations in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act (Cap 276) (Republic of Singapore) and such registration has not been cancelled at the time of accident loss or damage.

Limitation as to Use^:

- (a) Use for carriage of passengers or goods in connection with the Policyholder's business.
- (b) Use for social, domestic and pleasure purposes and business purposes of any person to whom the vehicle is
- ^ Limitation rendered inoperative by Section 8 of Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Policy does not cover:

- (a) Use for racing, pace-making, reliability trials or speed-testing.
- (b) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.
- (c) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

27 December 2022

Issue Date

Hicham Raissi **Chief Executive Officer** Allianz Insurance Singapore Pte. Ltd.

: 0000256 MARSH (SINGAPORE) PTE. LTD. Intermediary Code

: Section 1: Own Damage Excess

S\$ 900.00 Section 1: Windscreen 5\$ 100.00 Section 2: Liabilities to Third Parties 5\$ 0.00