

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S2M03RJQ Date: 17<sup>th</sup> Apr 2023

Our Ref: CS3/ASM22000900/Dwp3e2-1

## M/s HSBC Life (Singapore) Pte Ltd

C/o Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBR 7104U INSURED VEHICLE: EK 9988Z ACCIDENT DATE: 17/01/2022

110 01221 (1 211121 11, 01, 2022

We thank you for your instruction on 10/04/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBR 7104U from M/s Aeon Auto Consultant LLP.
- b) Singapore Accident Statement and Police Report of Vehicles FBR 7104U and EK 9988Z.
- c) Final Repair Bill of FBR 7104U from M/s Bikers Avenue.
- d) Colour damaged vehicle photographs of FBR 7104U.

Pre-Repair Inspection Date: 26/01/2022 at M/s Bikers Avenue Pte Ltd, No 1 Bukit Batok Crescent #02-58 Wcega Plaza, Singapore 658064.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FBR 7104U

Make & Model : Honda ADV150A

Year of Registration : 2020

Chassis Number : KF381007150

Engine Capacity : 149 cc

- 2. We recommend that the repairs of the entire damage require about <u>3 (Three)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.