



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800
Officer in Charge : VIVIAN TAN EE WI
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD 3 MEDIA CLOSE #07-03 SINGAPORE 138498
Attn :
Tel :
Fax No. :

Quotation No. : QO23/04-1043	Quotation Date : 08/04/2023	Terms : 60 DAYS
Vehicle No. : SNH6095D	Chassis No. : KMHC851CVNU296390	Policy Number :
Model : HYUNDAI IONIQ		Date of Accident : 06/04/2023
Third Party Insurer :		TP Vehicle No. : 97148MID
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>de</i>	1	659.6000	659.60 ✓
2	REAR BUMPER SIDE RETAINER (RHS) <i>new 7. x n</i>	1	83.0000	83.00
3	REAR BUMPER BRACKET (RHS) <i>7. x n</i>	1	68.0000	68.00
4	REAR BUMPER CLIPS @ 10PCS <i>new</i>	10	4.5000	45.00 ✓
5	REAR BUMPER CENTER COVER (GUNMETAL COLOUR) <i>3ea</i>	1	451.2000	451.20 ✓
6	REAR BUMPER REFLECTOR (RHS) <i>x n</i>	1	61.9000	61.90
7	REAR TAILGATE <i>lt</i>	1	2,840.4000	2,840.40 ✓
8	REAR TAILGATE "HYUNDAI" EMBLEM <i>new</i>	1	68.0000	68.00 ✓
9	REAR TAILGATE "IONIQ" BADGE <i>new</i>	1	65.0000	65.00 ✓
10	REAR TAILGATE "HYBRID" BADGE <i>new</i>	1	60.0000	60.00 ✓
11	REAR TAILGATE HINGE @ 2PCS <i>x n</i>	2	85.0000	170.00
12	REAR TAILGATE ABSORBER @ 2PCS <i>x n</i>	2	189.0000	378.00
13	REAR TAILGATE SPOILER <i>cm</i>	1	765.4000	765.40 ✓
14	REAR TAILGATE 3RD BRAKE LIGHT <i>cm</i>	1	192.0000	192.00 ✓
15	REAR TAILGATE INNER TRIM BOARD <i>5ea</i>	1	369.7000	369.70 ✓
16	REAR TAILGATE INNER TRIM BOARD CLIPS @ 10PCS <i>new</i>	10	5.5000	55.00 ✓
17	REAR TAILGATE REFLECTOR @ 2PCS (1PC) RH <i>cm</i>	2	794.4000 ✓	1,588.80
18	REAR TAILGATE LOWER GLASS <i>bno</i>	1	384.9000	384.90 ✓
19	REAR TAILGATE WINDSCREEN GLASS MOULDING <i>new</i>	1	125.0000	125.00 ✓
20	REAR TAILGATE SIDE FRAME @ 2PCS <i>x n</i>	2	129.0000	258.00
21	REAR FENDER (RHS) <i>bno repair x</i>	1	1,798.3000	1,798.30
22	REAR FENDER INNER TRIM BOARD (RHS) <i>x n</i>	1	356.0000	356.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : VIVIAN TAN EE WI Tel : Email :	GRAB RENTALS PTE LTD 3 MEDIA CLOSE #07-03 SINGAPORE 138498 Attn : Tel : Fax No. :

Quotation No. : QO23/04-1043	Quotation Date : 08/04/2023	Terms : 60 DAYS
Vehicle No. : SNH6095D	Chassis No. : KMHC851CVNU296390	Policy Number :
Model : HYUNDAI IONIQ		Date of Accident : 06/04/2023
Third Party Insurer :		TP Vehicle No. : 97148MID
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
23	REAR FENDER (LHS) - REPAIR	1		
24	REAR FENDER INNER TRIM BOARD CLIPS @ 10PCS <i>Xⁿⁿ 7164</i>	10	5.5000	55.00
25	REAR TAILLAMP @ 2PCS <i>1pc - RH can / 20%</i>	21	870.4000	1,740.80
26	REAR TAILLAMP CLIPS @ 6PCS <i>3 pcs / 621120</i>	3	12.0000	36.00
27	REAR TAILLAMP PANEL (RHS) <i>Xⁿⁿ</i>	1	218.9000	218.90
28	REAR END PANEL - REPAIR	1		
29	LESS 20%	1	-2,578.7800	-2,578.78
30	REAR REVERSE SENSOR @ 1SET <i>Xⁿⁿ</i>	1	280.0000	280.00
31	REAR NO PLATE & CASING <i>Xⁿⁿ</i>	1	80.0000	80.00
32	REAR WINDSCREEN GLASS SEALANT <i>new</i>	1	80.0000	80.00
33	REAR BUMPER CLEAR STICKER <i>new</i>	1	40.0000	40.00
34	TO REMOVE & REPLACED REAR REVERSE SENSOR.	1	100.0000	100.00
35	TO REMOVE & INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS. <i>Xⁿⁿ</i>	1	380.0000	380.00
36	TO REMOVE & REFIX BACK REAR LOWER & UPPER WINDSCREEN GLASS.	1	300.0000	300.00
37	TO REMOVE & TRANSFER REAR TAILGATE MECHANISM TO THE NEW TAILGATE.	1	150.0000	150.00
38	TO REMOVE & RESTORE BACK INNER TRIMMINGS, GARNISHES, SEAT AND ROOF LINING FOR FACILITATE REPAIR.	1	120.0000	120.00
39	TO REMOVE & REARRANGE REAR ELECTRICAL WIRING FOR FACILITATE REPAIR.	1	100.0000	100.00
40	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.	1	120.0000	120.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : VIVIAN TAN EE WI Tel : Email :	Customer : GRAB RENTALS PTE LTD 3 MEDIA CLOSE #07-03 SINGAPORE 138498 Attn : Tel : Fax No. :
---	---

Quotation No. : QO23/04-1043	Quotation Date : 08/04/2023	Terms : 60 DAYS
Vehicle No. : SNH6095D	Chassis No. : KMHC851CVNU296390	Policy Number :
Model : HYUNDAI IONIQ	Date of Accident : 06/04/2023	
Third Party Insurer :	TP Vehicle No. : 97148MID	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
41	TO KNOCKING & PANEL BEATING.	1	2,500.0000	2,500.00
42	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.	1	1,400.0000	1,400.00

6211.20
60.00
2630.00
8901.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
8 days
P/P
11/04/23 @ 1220
Resurvey before
paint

Sub Total	15,965.12
GST(8.00%)	1,277.21
Total (SGD)	17,242.33

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800