



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: CYNTHIA			Ref: CC4/HSB23003811/Apa3q2 Date: 19/07/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3636X	Veh. Inspected	SJT 28Y	
Policy No.	P2478218	Coverage (\$)	0.00	
Claim No.	S3M04LG5	Excess (\$)	0.00	
Assign From		Assign Date	11/04/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VELLFIRE	c.c	2493	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	AGH300193321	Colour	BRONZE	
Odometer	100252 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	MICHELIN	6 mm	
L/H Front Tyre	235/50 R18	MICHELIN	6 mm	
R/H Rear Tyre	235/50 R18	MICHELIN	6 mm	
L/H Rear Tyre	235/50 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/04/2023	Inspection Date	11/04/2023	
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	