

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

*not authorized
in
work
13/4/23*

M/S : LONPAC INSURANCE BHD
300 Beach Road #17-04/06
The Concourse
Singapore 199555

TEL: FAX:
ATTN: Motor Claim Department

ESTIMATE

No : 23041208
Date : 12/04/2023
Policy No : 11093188
Veh Reg No : SDT1909U
Make / Model : TOYOTA PREVIA
Your Ref No : 23/LP/TP-083(04)
Claim Type : TP CLAIM
Accident Date : 11/04/2023

*1/55
5 days
take photo after repair*

Discription	Quantity	List Price	Amount
Cost Price			S\$ S\$
1 FRT BONNET <i>Buc</i>	1 PC		\$245.00
2 FRT BONNET HINGES <i>Bent</i>	2 PCS		\$100.00
3 FRT BONNET LOCK <i>100</i>	1 PC		\$65.00
4 FRT BONNET INSULATOR <i>11</i>	1 PC		\$120.00
5 INSULATOR CLIPS <i>1 PC</i>	8 PCS		\$16.00
6 FRT GRILLE <i>one</i>	1 PC		\$245.00
7 GRILLE OUTER GARNISH <i>one</i>	1 PC		145
8 GRILLE CENTRE LOGO <i>one</i>	1 PC		\$50.00
9 GRILLE CLIPS <i>one</i>	4 PCS		\$8.00
10 FRT BUMPER <i>Dis</i>	1 PC		\$350.00
11 FRT BUMPER CLIPS <i>one</i>	10 PCS		\$20.00
12 HEADLAMP MID <i>holder one / raw</i>	2 PCS	750 \$475.00	1500 \$950.00
13 HEADLAMP SUPPORT PANEL <i>sent</i>	1 PC		\$580.00
14 FRT BUMPER REINFORCEMENT <i>2</i>	1 PC		\$150.00
15 BRACE PANEL <i>Bent</i>	1 PC		\$65.00
16 AIRCON CONDENSER <i>Bent / pan</i>	1 PC		\$580.00
17 RADIATOR <i>Bent / pan</i>	1 PC		\$650.00
18 RADIATOR MOTOR	1 PC		\$195.00
19 RADIATOR MOTOR COWLING <i>one</i>	1 PC		\$175.00
20 RADIATOR FAN BLADE	1 PC		\$95.00
21 RADIATOR TOP HOSE	1 PC		\$45.00
22 FRT BUMPER TOP RUBBER SEAL <i>70.00</i>	1 PC		\$50.00
23 RADIATOR TOP GARNISH <i>Dis</i>	1 PC		\$65.00
24 RADIATOR SPARE TANK <i>tank</i>	1 PC		\$175.00
25 WASHER TANK NECK <i>re</i>	1 PC		\$30.00
26 AIRCON LIQUID PIPE <i>one NO STOCK</i>	1 PC		\$450.00
27 AIRCON DISCHARGE PIPE <i>one</i>	1 PC		\$195.00
28 AIRCON COOLING PIPE <i>one</i>	1 PC		\$280.00
29 RADIATOR TOP BRACKET <i>Bent</i>	2 PCS	\$28.00	\$56.00
30 BATTERY BRACKET <i>Bent</i>	1 PC		\$50.00
31 RESONATOR BOX <i>one</i>	1 PC		\$95.00
32 HEADLAMP SUPPORT TOP GARNISH <i>one</i>	1 PC		\$145.00
33 TOP GARNISH CLIPS <i>one</i>	8 PCS		\$16.00

*upper blower neck 65 ?
Air intake hose 95 Dis ✓
Air cleaner box 380 one ✓
Engine oil dipstick 38 Daye ✓
Radiator cowling 175*

TOTAL \$6,311.00
Add 20% \$1,262.20
\$7,573.20

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg

GST:201119451E RCB NO:201119451E

M/S : LONPAC INSURANCE BHD
300 Beach Road #17-04/06
The Concourse
Singapore 199555

TEL: FAX:
ATTN: Motor Claim Department

ESTIMATE

No : 23041208
Date : 12/04/2023
Policy No : 11093188
Veh Reg No : SDT1909U
Make / Model : TOYOTA PREVIA
Your Ref No : 23/LP/TP-083(04)
Claim Type : TP CLAIM
Accident Date : 11/04/2023

Discription	Quantity	List Price	Amount
SPECIAL NET:			S\$ S\$
1 RADIATOR COOLANT <i>net</i>			\$25.00 <i>20</i>
TOTAL			<u>\$25.00</u>
Labour			
1 WIRE CHECKING			<i>20</i> \$30.00
2 REMOVE & REFIX AIRCON AND GAS			\$100.00 ✓
3 LABOUR CHARGE			<i>600</i> \$700.00
4 SPRAY PAINTING			<i>600</i> \$700.00
TOTAL			<u>\$1,530.00</u>

Amount Before Excess	\$9,128.20
Add GST @8%	\$730.26
Total Amount Payable	<u>\$9,858.46</u>

For SME MOTOR PTE LTD



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: