

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0368/2023/EQ
DATE : 12-Apr-23
WIP : 15794

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/4/2023
YOUR INSURED VEH NO : SLM 3566 D

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

OWNER'S NAME : MRS TEO KAH SAN, EMILIA
ADDRESS : 54 JOO CHIAT AVENUE
SINGAPORE 428164

TELEPHONE : HP +65 97411420
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210010975-01
VEHICLE NO : **EN 3589 R**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 29/1/2021
ENGINE NO : CZD C21271
CHASSIS NO : WAUZZZF3XM1050047
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Apr-23
PLACE OF ACCIDENT : CHANGI ROAD CLOSE TO INTERSECTION WITH STILL ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE EN 3589 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	500 ✓
3	TO RESPRAY REAR BUMPER AND REAR LID.	\$ 2,500.00	1100 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,652.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EN 3589 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Regis</i>	1	\$ 1,839.00	+
2	REAR BUMPER FIXING PARTS <i>see n</i>	1	\$ 230.00	+
3	REAR BUMPER SPOILER <i>crushed</i>	1	\$ 540.00	✓
4	REAR BUMPER TOW EYE COVER <i>see n</i>	1	\$ 51.00	+
5	REAR BUMPER CROSS REINFORCEMENT - CENTER <i>Regis</i>	1	\$ 114.00	+
6	REAR BUMPER BRACKET <i>3 not</i>	1	\$ 57.00	+
7	REAR BUMPER REFLECTOR - LH / RH <i>see n</i>	2	\$ 98.00	+
8	REAR BOOT LID OPENING CONTROL UNIT <i>3 not</i>	1	\$ 491.00	+
9	REAR TAILGATE OPENING SENSOR LINE <i>see n</i>	1	\$ 230.00	+
10	REAR AERIAL KEY ACCESS <i>see n</i>	1	\$ 81.00	+
11	REAR BUMPER REINFORCEMENT BEAM <i>3 not</i>	1	\$ 736.00	+
12	REAR BUMPER HOLDING STRAP - LH / RH <i>see n</i>	2	\$ 68.00	+
13	REAR BUMPER GUIDE SECTION - LH / RH <i>see n</i>	2	\$ 150.00	+
14	REAR PARKING AID SENSOR - INNER / OUTER <i>see n</i>	3	\$ 815.00	+
15	REAR PARKING AID SEAL RING <i>see n</i>	4	\$ 11.00	+
16	REAR WHEEL COVER - LH / RH <i>see n</i>	2	\$ 598.00	✓
17	PACKING ADHESIVE <i>3 not</i>	1	\$ 22.00	✓
18	AUDI EMBLEM <i>see n</i>	1	\$ 152.00	✓
19	"Q3" INSCRIPTION <i>see n</i>	1	\$ 110.00	✓
20	SUNDRIES <i>?</i>		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 6,793.00	
TOTAL LABOUR CHARGES		:	\$ 4,652.00	
GRAND TOTAL		:	\$ 11,445.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *14/04/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT