

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 12.04.2023

MODEL: Hyundai Ioniq

VEHICLE NO.: SH 7964E

LKK-

INSURANCE: INCOME CP/P

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	WING MIRROR LH	1		\$ 1,391.70
	LESS 20%			\$ 278.34
	PART TOTAL			\$ 1,113.36
	<u>Labour Charge</u>			
	Panel Beating			\$ 400.00
	Spray Painting			\$ 300.00
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 1,813.36

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjit 97495499
 12/4/23 @ 4:10pm
 01 day
 tanjit@heart.com
 Resurvey new parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by: