



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                        |                      |
|--|--|------------------------|----------------------|
| ALLIANZ INSURANCE SINGAPORE PTE LTD  |  | Ref:                   | CS3/AIS23003871/Svp3 |
| 79 ROBINSON ROAD   |  | Date:                  | 14/04/2023           |
| #09-01 SINGAPORE 068897  |  | Code:                  | AIS                  |
| <b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>  |  |                        |                      |
| <b>Insured Veh.</b>  | GBD 7107K  | <b>Veh. Inspected</b>  | SLB 2360U            |
| <b>Policy No.</b>  |  | <b>Coverage (\$)</b>   | 0.00                 |
| <b>Claim No.</b>   | 2023 32007166KC  | <b>Excess (\$)</b>     | 0.00                 |
| <b>Assign From</b>   | SHANTI   | <b>Assign Date</b>     | 13/04/2023           |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                        |                      |
| <b>Make &amp; Model</b>  |  | <b>c.c</b>             | 0                    |
| <b>Engine No.</b>  | HIDDEN   | <b>Year of Reg.</b>    |                      |
| <b>Chassis No.</b>   |  | <b>Colour</b>          |                      |
| <b>Odometer</b>  | -  | <b>Steering</b>        |                      |
| <b>Brakes</b>  |  | <b>Modification</b>    |                      |
| <b>General</b>   |  |                        |                      |
| <b>3. Conditions of Tyres</b>  |  |                        |                      |
|  | <b>Size</b>  | <b>Make</b>            | <b>Balance</b>       |
| <b>R/H Front Tyre</b>  |  |                        | mm                   |
| <b>L/H Front Tyre</b>  |  |                        | mm                   |
| <b>R/H Rear Tyre</b>   |  |                        | mm                   |
| <b>L/H Rear Tyre</b>   |  |                        | mm                   |
| <b>4. Description of Damages</b>   |  |                        |                      |
|  |  |                        |                      |
| <b>5. General Information</b>  |  |                        |                      |
| <b>Accident Date</b>   | 10/04/2023   | <b>Inspection Date</b> | 13/04/2023           |
| <b>Survey held at</b>  | TAN ENG HUAT MOTOR<br>BLK 6 DEFU LANE 10 #01-556 .<br>SINGAPORE 539187 |                        |                      |
| <b>5a. Remarks</b>   |  |                        |                      |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |  |                        |                      |