



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                        |                |
|--|--|------------------------|----------------|
| HSBC LIFE (SINGAPORE) PTE LTD  |  | Ref: CS/HSB23003888/p3 |                |
| 10 MARINA BOULEVARD  |  | Date: 14/04/2023       |                |
| #48-01 MARINA BAY FINANCIAL CENTRE TOWER   |  |                        |                |
| 2SINGAPORE 018983  |  | Code: HSB              |                |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                        |                |
| <b>Insured Veh.</b>  | SHB 6252U  | <b>Veh. Inspected</b>  | SMZ 5765C      |
| <b>Policy No.</b>  |  | <b>Coverage (\$)</b>   | 0.00           |
| <b>Claim No.</b>   | S3M04LL7   | <b>Excess (\$)</b>     | 0.00           |
| <b>Assign From</b>   | OH VALE  | <b>Assign Date</b>     | 14/04/2023     |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                        |                |
| <b>Make &amp; Model</b>  |  | <b>c.c</b>             | 0              |
| <b>Engine No.</b>  | HIDDEN   | <b>Year of Reg.</b>    |                |
| <b>Chassis No.</b>   |  | <b>Colour</b>          |                |
| <b>Odometer</b>  | -  | <b>Steering</b>        |                |
| <b>Brakes</b>  |  | <b>Modification</b>    |                |
| <b>General</b>   |  |                        |                |
| <b>3. Conditions of Tyres</b>  |  |                        |                |
|  | <b>Size</b>  | <b>Make</b>            | <b>Balance</b> |
| <b>R/H Front Tyre</b>  |  |                        | mm             |
| <b>L/H Front Tyre</b>  |  |                        | mm             |
| <b>R/H Rear Tyre</b>   |  |                        | mm             |
| <b>L/H Rear Tyre</b>   |  |                        | mm             |
| <b>4. Description of Damages</b>   |  |                        |                |
|  |  |                        |                |
| <b>5. General Information</b>  |  |                        |                |
| <b>Accident Date</b>   | 12/04/2023   | <b>Inspection Date</b> |                |
| <b>Survey held at</b>  | TICK HAI MOTOR & WELDING SERVICES<br>BLK 1 KAKI BUKIT AVE 6<br>#01-54 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |                        |                |
| <b>5a. Remarks</b>   |  |                        |                |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                        |                |